

Device	XMC4400
Marking/Step	EES-AA, ES-AA
Package	PG-LQFP-64/100

Overview

Document ID is **02512AERRA**.

This “Errata Sheet” describes product deviations with respect to the user documentation listed below.

Table 1 Current User Documentation

Document	Version	Date
XMC4400 Reference Manual	V1.5	April 2014
XMC4400 Data Sheet	V1.1	March 2014

Make sure that you always use the latest documentation for this device listed in category “Documents” at <http://www.infineon.com/xmc4000>.

Notes

- 1. The errata described in this sheet apply to all temperature and frequency versions and to all memory size and configuration variants of affected devices, unless explicitly noted otherwise.*
- 2. Devices marked with EES or ES are engineering samples which may not be completely tested in all functional and electrical characteristics, therefore they must be used for evaluation only. Specific test conditions for EES and ES are documented in a separate “Status Sheet”, delivered with the device.*
- 3. XMC4000 devices are equipped with an ARM® Cortex™-M4 core. Some of the errata have a workaround which may be supported by some compiler tools. In order to make use of the workaround the corresponding compiler switches may need to be set.*

Conventions used in this Document

Each erratum is identified by **Module_Marker.TypeNumber**:

- **Module**: Subsystem, peripheral, or function affected by the erratum.
- **Marker**: Used only by Infineon internal.
- **Type**: type of deviation
 - **(none)**: Functional Deviation
 - **P**: Parametric Deviation
 - **H**: Application Hint
 - **D**: Documentation Update
- **Number**: Ascending sequential number. As this sequence is used over several derivatives, including already solved deviations, gaps inside this enumeration can occur.

1 History List / Change Summary

Table 2 History List

Version	Date	Remark
1.0	2013-02	Initial Version
1.1	2013-05	Added: PORTS_CM.005, STARTUP_CM.001
1.2	2013-09	Added: ADC_AI.008, CCU8_AI.002, CCU8_AI.004, CPU_CM.004, HRPWM_AI.003. Updated: RESET_CM.H001
1.3	2014-04	This Document. For changes see column "Chg" in the tables below.

Table 3 Errata fixed in this step

Errata	Short Description	Change
- none -		

Table 4 Functional Deviations

Functional Deviation	Short Description	Chg	Pg
ADC_AI.002	Result of Injected Conversion may be wrong		7
ADC_AI.008	Wait-for-Read condition for register GLOBRES not detected in continuous auto-scan sequence		7
ADC_TC.064	Effect of conversions in 10-bit fast compare mode on post-calibration	New	8
CCU8_AI.002	CC82 Timer of the CCU8x module cannot use the external shadow transfer trigger connected to the POSIFx module		9
CCU8_AI.003	CCU8 Parity Checker Interrupt Status is cleared automatically by hardware		11

Table 4 Functional Deviations (cont'd)

Functional Deviation	Short Description	Chg	Pg
CCU8_AI.004	CCU8 output PWM glitch when using low side modulation via the Multi Channel Mode		14
CCU_AI.002	CCU4 and CCU8 Prescaler synchronization clear does not work when Module Clock is faster than Peripheral Bus Clock		17
CCU_AI.004	CCU4 and CCU8 Extended Read Back loss of data		18
CCU_AI.005	CCU4 and CCU8 External IP clock Usage		19
CPU_CM.001	Interrupted loads to SP can cause erroneous behavior		21
CPU_CM.004	VDIV or VSQRT instructions might not complete correctly when very short ISRs are used		23
DSD_AI.001	Possible Result Overflow with Certain Decimation Factors	New	24
ETH_AI.001	Incorrect IP Payload Checksum at incorrect location for IPv6 packets with Authentication extension header		25
ETH_AI.002	Incorrect IP Payload Checksum Error status when IPv6 packet with Authentication extension header is received		26
ETH_AI.003	Overflow Status bits of Missed Frame and Buffer Overflow counters get cleared without a Read operation		27
ETH_CM.001	Ethernet module synchronization limits CPU frequency		28

Table 4 Functional Deviations (cont'd)

Functional Deviation	Short Description	Chg	Pg
HRPWM_AI.001	HRPWM output signal interference while using two control sources		28
HRPWM_AI.003	HRPWM Usage Limitations		30
HRPWM_AI.004	HRPWM Peripheral Bus Clock Limitation	New	33
LEDTS_AI.001	Delay in the update of FNCTL.PADT bit field		34
PMU_CM.001	Branch from non-cacheable to cacheable address space instruction may corrupt the program execution		38
PORTS_CM.002	P0.9 Pull-up permanently active		40
PORTS_CM.005	Different PORT register reset values after module reset		41
POSIF_AI.001	Input Index signal from Rotary Encoder is not decoded when the length is 1/4 of the tick period		42
SCU_CM.006	Deep sleep entry with PLL power-down option generates SOSCWDGT and SVCOLCKT trap		44
SCU_CM.015	Parity Memory Test function not usable	New	45
STARTUP_CM.001	CAN Bootstrap Loader		45
USIC_AI.008	SSC delay compensation feature cannot be used	New	45
USIC_AI.010	Minimum and maximum supported word and frame length in multi-IO SSC modes		46
USIC_AI.013	SCTR register bit fields DSM and HPCDIR are not shadowed with start of data word transfer		46
USIC_AI.014	No serial transfer possible while running capture mode timer		47

Table 4 Functional Deviations (cont'd)

Functional Deviation	Short Description	Chg	Pg
USIC_AI.015	Wrong generation of FIFO standard transmit/receive buffer events when TBCTR.STBTEN/RBCTR.SRBTEN = 1		47
USIC_AI.016	Transmit parameters are updated during FIFO buffer bypass		47
USIC_AI.017	Clock phase of data shift in SSC slave cannot be changed		48
USIC_AI.018	Clearing PSR.MSLS bit immediately deasserts the SELOx output signal		48
USIC_AI.019	First data word received by IIC receiver triggers RIF instead of AIF		49
USIC_AI.020	Handling unused DOUT lines in multi-IO SSC mode	New	50

Table 5 Application Hints

Hint	Short Description	Chg	Pg
ADC_AI.H004	Completion of Startup Calibration		51
ADC_TC.H011	Bit DCMSB in register GLOBCFG	New	51
MultiCAN_AI.H005	TxD Pulse upon short disable request		51
MultiCAN_AI.H006	Time stamp influenced by resynchronization		52
MultiCAN_AI.H007	Alert Interrupt Behavior in case of Bus-Off		52
MultiCAN_AI.H008	Effect of CANDIS on SUSACK		53
MultiCAN_TC.H003	Message may be discarded before transmission in STT mode		53
MultiCAN_TC.H004	Double remote request		53
RESET_CM.H001	Power-On Reset Release		54

2 Functional Deviations

The errata in this section describe deviations from the documented functional behavior.

ADC AI.002 Result of Injected Conversion may be wrong

In cancel-inject-repeat mode ($GxARBPR.CSM^* = 1_B$), the result of the higher prioritized injected conversion c_H may be wrong if it was requested within a certain time window at the end of a lower prioritized conversion c_L . The width of the critical window depends on the divider factor $DIVA$ for the analog internal clock.

Workaround

Do not use cancel-inject-repeat mode. Instead, use wait-for-start mode ($GxARBPR.CSM^* = 0_B$).

ADC AI.008 Wait-for-Read condition for register GLOBRES not detected in continuous auto-scan sequence

In the following scenario:

- A continuous auto-scan is performed over several ADC groups and channels by the Background Scan Source, using the global result register (GLOBRES) as result target ($GxCHCTRY.RESTBS=1_B$), and
 - The Wait-for-Read mode for GLOBRES is enabled ($GLOBRCR.WFR=1_B$),
- each conversion of the auto-scan sequence has to wait for its start until the result of the previous conversion has been read out of GLOBRES.

When the last channel of the auto-scan is converted and its result written to GLOBRES, the auto-scan re-starts with the highest channel number of the highest ADC group number. But the start of this channel does not wait until the result of the lowest channel of the previous sequence has been read from register GLOBRES, i.e. the result of the lowest channel may be lost.

Workaround

If either the last or the first channel in the auto-scan sequence does not write its result into GLOBRES, but instead into its group result register (selected via bit GxCHCTry.RESTBS=0_B), then the Wait-for-Read feature for GLOBRES works correctly for all other channels of the auto-scan sequence.

For this purpose, the auto-scan sequence may be extended by a “dummy” conversion of group x/ channel y, where the Wait-for-Read mode must not be selected (GxRCRy.WFR=0_B) if the result of this “dummy” conversion is not read.

ADC_TC.064 Effect of conversions in 10-bit fast compare mode on post-calibration

The calibrated converters Gx (x = 0..3) support post-calibration. Unless disabled by software (via bits GLOBCFG.DPCALx = 0), a calibration step is performed after each conversion, incrementally increasing/decreasing internal calibration values to compensate process, temperature, and voltage variations.

If a conversion in 10-bit fast-compare mode (bit field CMS/E = 101_B in corresponding Input Class register) is performed between two conversions in other (non-fast-compare) modes on a converter Gx, the information gained from the last post-calibration step is disturbed. This will lead to a slightly less accurate result of the next conversion in a non-fast-compare mode.

Depending on the ratio of conversions in fast-compare mode versus conversions in other modes, this effect will be more or less obvious.

In a worst case scenario (fast-compare with a constant result injected between each two normal conversions), all calibration values can drift to their maxima / minima, causing the converter Gx to deliver considerably inaccurate results.

Workaround

Do not perform conversions using 10-bit fast-compare mode on the calibrated converters Gx (x = 0..3). Instead, use the uncalibrated converters Gy (y = 4..7) to perform conversions in fast-compare mode.

CCU8 AI.002 CC82 Timer of the CCU8x module cannot use the external shadow transfer trigger connected to the POSIFx module

Each CCU8 Module Slice contains 4 identical timers (CC80, CC81, CC82 and CC83). There is the possibility of updating the values controlling the duty cycle, period, output passive level, dither and floating prescaler on-the-fly of each and every timer, with a SW request. The update request of these values can also be done via an external trigger that is connected to the POSIFx module Figure 1. An update action of any of these values is named as “shadow transfer”.

The signal between the POSIFx and CCU8x module is used to handshake a concurrent update between several registers, contained in the two modules. The output signal of the POSIFx is named as POSIFx.OUT6 while the input signal on the CCU8x side is named as CCU8x.MCSS.

value needs to be done. After that timeframe, the POSIF waits for the handshake trigger of the CCU8x Timer to indicate that an update is going to be performed. At this specific time, both the values of the CCU8x Timer and POSIF are update completely synchronous.

This feature cannot be used with the Timer2 (defined as CC82 in the documentation) of the CCU8x module(s) (more than one CCU8 module can be contained on a specific device).

All the other 3 Timers (defined as CC80, CC81, CC83) inside the CCU8x modul are not affected by this issue.




Figure 2 Value update handshake between CCU8x and POSIFx

Workaround

None

CCU8 AI.003 CCU8 Parity Checker Interrupt Status is cleared automatically by hardware

Each CCU8 Module Timer has an associated interrupt status register. This Status register, CC8yINTS, keeps the information about which interrupt source

triggered an interrupt. The status of this interrupt source can only be cleared by software. This is an advantage because the user can configure multiple interrupt sources to the same interrupt line and in each triggered interrupt routine, it reads back the status register to know which was the origin of the interrupt.

Each CCU8 module also contains a function called Parity Checker. This Parity Checker function, crosschecks the output of a XOR structure versus an input signal, as seen in Figure 1.

When using the parity checker function, the associated status bitfield, is cleared automatically by hardware in the next PWM cycle whenever an error is not present.

This means that if in the previous PWM cycle an error was detected and one interrupt was triggered, the software needs to read back the status register before the end of the immediately next PWM cycle.

This is indeed only necessary if multiple interrupt sources are ORed together in the same interrupt line. If this is not the case and the parity checker error source is the only one associated with an interrupt line, then there is no need to read back the status information. This is due to the fact, that only one action can be triggered in the software routine, the one linked with the parity checker error.




Figure 3 Parity Checker diagram

Workaround

Not ORing the Parity Checker error interrupt with any other interrupt source. With this approach, the software does not need to read back the status information to understand what was the origin of the interrupt - because there is only one source.

CCU8 AI.004 CCU8 output PWM glitch when using low side modulation via the Multi Channel Mode

Each CCU8 Timer Slice can be configured to use the Multi Channel Mode - this is done by setting the CC8yTC.MCME1 and/or CC8yTC.MCME2 bit fields to 1_B. Each bit field enables the multi channel mode for the associated compare channel of the CCU8 Timer Slice (each CCU8 Timer Slice has two compare channels that are able to generate each a complementary pair of PWM outputs).

After enabled, the Multi Channel mode is then controlled by several input signals, one signal per output. Whenever an input is active, the specific PWM output is set to passive level - Figure 1.

The Multi Channel mode is normally used to modulate in parallel several PWM outputs (a complete CCU8 - up to 16 PWM signals can be modulated in parallel).

A normal use case is the parallel control of the PWM output for BLDC motor control. In Figure 2, we can see the Multi Channel Pattern being updated synchronously to the PWM signals. Whenever a multi channel input is active (in this case 0), the specific output is set into passive level (the level in which the external switch is OFF).




Figure 4 Multi Channel Mode diagram




Figure 5 Multi Channel Mode applied to several CCU8 outputs

A glitch is present at the PWM outputs whenever the dead time of the specific compare channel is enabled - CC8yDTC.DTE1 and/or CC8yDTC.DTE2 set to 1_B (each compare channel has a separate dead time function) - and the specific multi channel pattern for the channel is 01_B or 10_B.

This glitch is not present if the specific timer slice is configure in symmetric edge aligned mode - CC8yTC.TCM = 0_B and CC8yCHC.ASE = 0_B.

This glitch only affects the PWM output that is linked to the inverting ST path of each compare channel (non inverting outputs are not affected).

The effect of this glitch can be seen in Figure 3. The duration of the PWM glitch has the same length has the dead time value programmed into the CC8yDC1R.DT1F field (for compare channel 1) or into the CC8yDC1R.DT2F.




Figure 6 PWM output glitch

Workaround

To avoid the glitch on the inverting path of the PWM output, one can disable the dead time function before the Multi Channel Pattern is set to 01_B or 10_B. Disabling the dead time of the inverting PWM output can be done by setting:

CC8yDTC.DCEN2 = 0 //if compare channel 1 is being used


```
CC8yDTC.DCEN4 = 0 //if compare channel 2 is being used
```

The dead time needs to be re enabled, before the complementary outputs become modulated at the same time:

```
CC8yDTC.DCEN2 = 1 //if compare channel 1 is being used
```

```
CC8yDTC.DCEN4 = 1 //if compare channel 2 is being used
```

CCU AI.002 CCU4 and CCU8 Prescaler synchronization clear does not work when Module Clock is faster than Peripheral Bus Clock

Each CCU4/CCU8 module contains a feature that allows to clear the prescaler division counter synchronized with the clear of a run bit of a Timer Slice. This is configure via the GCTRL.PRBC field. The default value of 000_B dictates that only the software can clear the prescaler internal division counter. Programming a value different from 000_B into the PRBC will impose that the prescaler division counter is cleared to 0_D whenever the selected Timer Slice (selected via the PRBC field) run bit is cleared (TRB bit field).

In normal operating conditions, clearing the internal prescaler division counter is not needed. The only situation were a clear of the division may be needed is when several Timer Slices inside one unit (CCU4/CCU8) are using different prescaling factors and a realignment of all the timer clocks is needed. This normally only has a benefit if there is a big difference between the prescaling values, e.g. Timer Slice 0 using a module clock divided by 2_D and Timer Slice 1 using a module clock divided by 1024_D .

When the peripheral bus clock frequency is smaller than the CCU4/CCU8 module clock frequency, $f_{\text{periph}} < f_{\text{CCU}}$, it is not possible to clear the prescaler division counter, synchronized with the clear of the run bit of one specific Timer Slice.

Workaround 1

The clearing of the prescaler internal division counter needs to be done via software: GCTRL.PRBC programmed with 000_B and whenever a clear is needed, writing 1_B into the GIDLS.CPRB bit field.

Workaround 2

When the usage of the Prescaler internal division clear needs to be synchronized with a timer run bit clear, the module clock of the CCU4/CCU8 should be equal to the peripheral bus clock frequency: $f_{\text{periph}} = f_{\text{CCU}}$.

To do this, the following SCU (System Control Unit) registers should be set with values that force this condition: CCUCLKCR.CCUDIV, CPUCLKCR.CPUDIV and PBCLKCR.PBDIV.

CCU AI.004 CCU4 and CCU8 Extended Read Back loss of data

Each CCU4/CCU8 Timer Slice contains a bit field that allows the enabling of the Extended Read Back feature. This is done by setting the CC8yTC.ECM/CC4yTC.ECM = 1_B . Setting this bit field to 1_B only has an impact if the specific Timer Slice is working in Capture Mode (CC8yCMC.CAP1S or CC8yCMC.CAP0S different from 00_B - same fields for CCU4).

By setting the bit field to ECM = 1_B , is then possible to read back the capture data of the specific Timer Slice (or multiple Timer Slices, if this bit field is set in more than one Timer Slice) through a single address. This address is linked to the ECRD register.

Referring to [Figure 7](#), the hardware every time that the software reads back from the ECRD address, will return the immediately next capture register that contains new data. This is done in a circular access, that contains all the capture registers from the Timer Slices that are working in capture mode.

When using this feature, there is the possibility of losing captured data within a Timer Slice. The data that is lost is always the last captured data within a timer slice, e.g. (with CCU4 nomenclature - same applies to CCU8):

- Timer X has 4 capture registers and is the only Timer set with ECM = 1_B . At the moment that the software starts reading the capture registers via the ECRD address, we have already captured four values. The ECRD read back will output CC4xC0V -> CC4xC1V -> CC4xC2V -> CC4xC3V (CC4xC3V value is lost)
- Timer X has 4 capture registers and is the only Timer set with ECM = 1_B . At the moment that the software starts reading the capture registers via the

ECRD address, we have already capture two values. The ECRD read back will output CC4xC2V -> CC4xC2V (CC4xC3V value is lost)

- Timer X and Timer Y have 4 capture registers each and they are both configured with ECM = 1_B. At the moment that the software starts reading the capture registers via the ECRD address, we have already capture two values on Timer X and 4 on Timer Y. The ECRD read back will output CC4xC0V -> CC4xC1V -> CC4xC2V -> CC4xC3V -> CC4yC2V -> CC4yC2V (CC4yC3V value is lost)




Figure 7 Extended Read Back access - example for CCU4 (CCU8 structure is the same)

Workaround

None.

CCU_AI.005 CCU4 and CCU8 External IP clock Usage

Each CCU4/CCU8 module offers the possibility of selecting an external signal to be used as the master clock for every timer inside the module Figure 1. External signal in this context is understood as a signal connected to other module/IP or connected to the device ports.

The user has the possibility after selecting what is the clock for the module (external signal or the clock provided by the system), to also select if this clock

Functional Deviations

needs to be divided. The division ratios start from 1 (no frequency division) up to 32768 (where the selected timer uses a frequency of the selected clock divided by 32768).

This division is selected by the PSIV field inside of the CC4yPSC/CC8yPSC register. Notice that each Timer Slice (CC4y/CC8y) have a specific PSIV field, which means that each timer can operate in a different frequency.

Currently is only possible to use an external signal as Timer Clock when a division ratio of 2 or higher is selected. When no division is selected (divided by 1), the external signal cannot be used.

The user must program the PSIV field of each Timer Slice with a value different from 0000_B - minimum division value is /2.

This is only applicable if the Module Clock provided by the system (the normal default configuration and use case scenario) is not being used. In the case that the normal clock configured and programmed at system level is being used, there is not any type of constraints.

One should not also confuse the usage of an external signal as clock for the module with the usage of an external signal for counting. These two features are completely unrelated and there are not any dependencies between both.




Figure 8 Clock Selection Diagram for CCU4/CCU8

Workaround

None.

CPU_CM.001 Interrupted loads to SP can cause erroneous behavior

If an interrupt occurs during the data-phase of a single word load to the stack-pointer (SP/R13), erroneous behavior can occur. In all cases, returning from the interrupt will result in the load instruction being executed an additional time. For all instructions performing an update to the base register, the base register will be erroneously updated on each execution, resulting in the stack-pointer being loaded from an incorrect memory location. The affected instructions that can result in the load transaction being repeated are:

1. LDR SP,[Rn],#imm
2. LDR SP,[Rn,#imm]!
3. LDR SP,[Rn,#imm]
4. LDR SP,[Rn]
5. LDR SP,[Rn,Rm]

The affected instructions that can result in the stack-pointer being loaded from an incorrect memory address are:

1. LDR SP,[Rn],#imm
2. LDR SP,[Rn,#imm]!

Conditions

1. An LDR is executed, with SP/R13 as the destination
2. The address for the LDR is successfully issued to the memory system
3. An interrupt is taken before the data has been returned and written to the stack-pointer.

Implications

Unless the load is being performed to Device or Strongly-Ordered memory, there should be no implications from the repetition of the load. In the unlikely event that the load is being performed to Device or Strongly-Ordered memory, the repeated read can result in the final stack-pointer value being different than had only a single load been performed.

Interruption of the two write-back forms of the instruction can result in both the base register value and final stack-pointer value being incorrect. This can result in apparent stack corruption and subsequent unintended modification of memory.

Workaround

Both issues may be worked around by replacing the direct load to the stack-pointer, with an intermediate load to a general-purpose register followed by a move to the stack-pointer.

If repeated reads are acceptable, then the base-update issue may be worked around by performing the stack pointer load without the base increment

followed by a subsequent ADD or SUB instruction to perform the appropriate update to the base register.

CPU_CM.004 VDIV or VSQRT instructions might not complete correctly when very short ISRs are used

The VDIV and VSQRT instructions take 14 cycles to execute. When an interrupt is taken a VDIV or VSQRT instruction is not terminated, and completes its execution while the interrupt stacking occurs. If lazy context save of floating point state is enabled then the automatic stacking of the floating point context does not occur until a floating point instruction is executed inside the interrupt service routine.

Lazy context save is enabled by default. When it is enabled, the minimum time for the first instruction in the interrupt service routine to start executing is 12 cycles. In certain timing conditions, and if there is only one or two instructions inside the interrupt service routine, then the VDIV or VSQRT instruction might not write its result to the register bank or to the FPSCR.

Conditions

1. The floating point unit is present and enabled
2. Lazy context saving is not disabled
3. A VDIV or VSQRT is executed
4. The destination register for the VDIV or VSQRT is one of s0 - s15
5. An interrupt occurs and is taken
6. The interrupt service routine being executed does not contain a floating point instruction
7. 14 cycles after the VDIV or VSQRT is executed, an interrupt return is executed

A minimum of 12 of these 14 cycles are utilized for the context state stacking, which leaves 2 cycles for instructions inside the interrupt service routine, or 2 wait states applied to the entire stacking sequence (which means that it is not a constant wait state for every access). In general this means that if the memory system inserts wait states for stack transactions then this erratum cannot be observed.

Implications

The VDIV or VQSRT instruction does not complete correctly and the register bank and FPSCR are not updated, meaning that these registers hold incorrect, out of date, data.

Workaround

A workaround is only required if the floating point unit is present and enabled. A workaround is not required if the memory system inserts one or more wait states to every stack transaction.

There are two workarounds:

1. Disable lazy context save of floating point state by clearing LSPEN to 0 (bit 30 of the FPCCR at address 0xE000EF34).
2. Ensure that every interrupt service routine contains more than 2 instructions in addition to the exception return instruction.

DSD AI.001 Possible Result Overflow with Certain Decimation Factors

Certain combinations of CIC filter grade and oversampling rate (see below) can lead to an overflow within the CIC filter. These combinations must be avoided to ensure proper operation of the digital filter.

Critical combinations:

- CIC2 (CFMC/CFAC = 01_B) with oversampling rate of 182
- CIC3 (CFMC/CFAC = 10_B) with oversampling rate of 33, 41, 51, 65, 81, 102, 129, 162... 182, 204
- CICF (CFMC/CFAC = 11_B) with oversampling rate of 129, 182

Note: Filter grade and oversampling rate are defined in register FCFGCx/FCFGAx. The shown oversampling rates are defined as CFMDF+1/CFADF+1.

Workaround

None.

ETH_AI.001 Incorrect IP Payload Checksum at incorrect location for IPv6 packets with Authentication extension header

When enabled, the Ethernet MAC computes and inserts the IP header checksum (IPv4) or TCP, UDP, or ICMP payload checksum in the transmitted IP datagram (IPv4 or IPv6) on per-packet basis. The Ethernet MAC processes the IPv6 header and the optional extension headers (if present) to identify the start of actual TCP, UDP, or ICMP payload for correct computation and insertion of payload checksum at appropriate location in the packet. The IPv6 header length is fixed (40 bytes) whereas the extension header length is specified in units of N bytes:

Extension Header Length Field Value x N bytes + 8 bytes

where N = 4 for authentication extension header and N = 8 for all other extension headers supported by the Ethernet MAC. If the actual payload bytes are less than the bytes indicated in the Payload Length field of the IP header, the Ethernet MAC indicates the IP Payload Checksum error.

If the payload checksum is enabled for an IPv6 packet containing the authentication extension header, then instead of bypassing the payload checksum insertion, the Ethernet MAC incorrectly processes the packet and inserts a payload checksum at an incorrect location. As a result, the packet gets corrupted, and it is dropped at the destination. The software should not enable the payload checksum insertion for such packets because the Integrity Check Value (ICV) in the authentication extension header is calculated and inserted considering that the payload data is immutable (not modified) in transit. Therefore, even if the payload checksum is correctly calculated and inserted, it results into a failure of the ICV check at the final destination and the packet is eventually dropped.

Workaround

The software should not enable the IP payload checksum insertion by the Ethernet MAC for Tx IPv6 packets with authentication extension headers. The software can compute and insert the IP payload checksum for such packets.

ETH_AI.002 Incorrect IP Payload Checksum Error status when IPv6 packet with Authentication extension header is received

The Ethernet MAC processes a TCP, UDP, or ICMP payload in the received IP datagrams (IPv4 or IPv6) and checks whether the received checksum field matches the computed value. The result of this operation is given as an IP Payload Checksum Error in the receive status word. This status bit is also set if the length of the TCP, UDP, or ICMP payload does not match the expected payload length given in the IP header.

In IPv6 packets, there can be optional extension headers before actual TCP, UDP, or ICMP payload. To compute and compare the payload checksum for such packets, the Ethernet MAC sequentially parses the extension headers, determines the extension header length, and identifies the start of actual TCP, UDP, or ICMP payload. The header length of all extension headers supported by the Ethernet MAC is specified in units of 8 bytes (Extension Header Length Field Value x 8 bytes + 8 bytes) except in the case of authentication extension header. For authentication extension header, the header length is specified in units of 4 bytes (Extension Header Length Field Value x 4 bytes + 8 bytes).

However, because of this defect, the Ethernet MAC incorrectly interprets the size of the authentication extension header in units of 8 bytes, because of which the following happens:

- Incorrect identification of the start of actual TCP, UDP, or ICMP payload
- Computing of incorrect payload checksum
- Comparison with incorrect payload checksum field in the received IPv6 frame that contains the authentication extension header
- Incorrect IP Payload Checksum Error status

As a result, the IP Payload checksum error status is generated for proper IPv6 packets with authentication extension header. If the Ethernet MAC core is programmed to drop such `error` packets, such packets are not forwarded to the host software stack.

Workaround

Disable dropping of TCP/IP Checksum Error Frames by setting Bit 26 (DT) in the Operation Mode Register (OPERATION_MODE). This enables the Ethernet MAC core to forward all packets with IP checksum error to the software driver.

The software driver must process all such IPv6 packets that have payload checksum error status and check whether they contain the authentication extension header. If authentication extension header is present, the software driver should either check the payload checksum or inform the upper software stack to check the packet for payload checksum.

ETH AI.003 Overflow Status bits of Missed Frame and Buffer Overflow counters get cleared without a Read operation

The DMA maintains two counters to track the number of frames missed because of the following:

- Rx Descriptor not being available
- Rx FIFO overflow during reception

The Missed Frame and Buffer Overflow Counter register indicates the current value of the missed frames and FIFO overflow frame counters. This register also has the Overflow status bits (Bit 16 and Bit 28) which indicate whether the rollover occurred for respective counter. These bits are set when respective counter rolls over. These bits should remain high until this register is read.

However, erroneously, when the counter rollover occurs second time after the status bit is set, the respective status bit is reset to zero.

Effects

The application may incorrectly detect that the rollover did not occur since the last read operation.

Workaround

The application should read the Missed Frame and Buffer Overflow Counter register periodically (or after the Overflow or Rollover status bits are set) such that the counter rollover does not occur twice between read operations.

ETH_CM.001 Ethernet module synchronization limits CPU frequency

Due to synchronization problems the Ethernet modules DMA data descriptor pointers may become corrupted. As a consequence the module delivers wrong data or fails to transfer data at all.

Workaround

Limit the CPU frequency to half of the System frequency ($f_{CPU} = f_{SYS}/2$) by setting bit field CPUDIV of register CPUCLKCR (CPUCLKCR.CPUDIV=1).

HRPWM_AI.001 HRPWM output signal interference while using two control sources

The High Resolution PWM (HRPWM) unit has 4 High Resolution Channel (HRC) sub modules. These are the sub modules that are used to extend the normal PWM resolution up to 150 ps. The structure of each of these sub modules is depicted in **Figure 9**.




Figure 9 High Resolution Channel (HRC) simplified block diagram

From the scheme of each HRC, it is possible to control the output PWM signal via two Source Selectors (Source Selector 0 and Source Selector 1). Each of these Source Selectors can generate a pair of PWM set and clear signals (that are propagated to the output control stage).

When both paths are being used (High Resolution Path and Low Resolution Path), the Source Selector 0 output signals always have priority over the signals generated via Source Selector 1.

At any given instant a bitfield that controls which Source Selector is connected to which path can be updated by Software, via the HRCyST.ST bitfield.

When only one path is used (only High Resolution Path or only High Resolution Path) the software can still update at any given time which is the Source Selector controlling this specific path (via the HRCyST.ST bitfield).

This scenario where only one path is enabled but both Source Selectors are being used, and by being used is understood that signals are being actively decoded from the Source Selectors (input signals for the Source Selectors are being updated) is depicted on **Figure 10** - in this example the High Resolution Path is the one being used.




Figure 10 HRC with only one path enabled and two Source Selectors

In the above scenario, every time that the HRCyST.ST bitfield is 1_B , the Source Selector 1 is the one that has control over the PWM signal. Whenever the HRCyST.ST bitfield is 0_B is the Source Selector 0 that has control over the PWM signal.

An issue exists whenever the Source Selector 1 is selected ($\text{HRCyST.ST} = 1_B$) and there is a collision between signals from both Source Selectors. A collision is understood as:

- at the same module clock time frame Source Selector 0 and Source Selector 1 both decode a signal (a PWM set or PWM clear).

If the described condition occurs, then the signal generated by Source Selector 1 is lost and the PWM signal is not handled properly - **Figure 11**.




Figure 11 Collision between signals of the two Source Selectors - valid only when HRCyST.ST = 1_B

Workaround 1

Ensuring that the signals controlling both Source Selectors are spaced by a minimum of 1 HRPWM module clock cycle. This is indeed only necessary if is currently Source Selector 1 the one selected to control the PWM path (HRCyST.ST = 1_B).

Workaround 2

Ensuring that the signals controlling Source Selector 0 are stopped whenever Source Selector 1 the one selected to control the PWM path (HRCyST.ST = 1_B).

HRPWM_AI.003 HRPWM Usage Limitations

The High Resolution PWM (HRPWM) is comprised of 4 High Resolution Channels (HRC) and 3 Comparator and Slope Generation sub modules. The general structure of the peripheral can be seen in [Figure 9](#) (HRPWM = 3xCSGs + 4xHRCs).

Each HRC sub module is able to generate a complementary PWM output signal with a resolution of 150 ps.

Functional Deviations

The CSG sub modules contain a high speed comparator and a 10 bit high speed DAC for reference generation. It is also possible to use the CSG to generate sawtooth and triangular waveforms via the 10 bit DAC.

Due to power connection issues, in this current device step, the CSG sub modules are not functional.

Also due to power connection issues, the HRC sub modules can have the following problems:

- High Resolution Channel 3 may stop working due to internal voltage drop.
- Generation of the 150 ps resolution of all the HRCs may not ramp up properly during module initialization (temperature dependency). If this happens, then all the HRC channels are not able to generate a 150 ps resolution. The proper ramp can be checked by polling the HRGHRS.HRGR bitfield.




Figure 12 High Resolution Channel (HRC) simplified block diagram

Workaround

None.

HRPWM AI.004 HRPWM Peripheral Bus Clock Limitation

The High Resolution PWM (HRPWM) peripheral uses two clocks generated by the SCU, the module clock (defined as f_{ccu} in the System Control Unit) and the peripheral bus clock (defined as f_{periph} in the System Control Unit).

The module clock is the one being used by the HRPWM kernel. The peripheral bus clock is the one being used by the interface between the CPU and the HRPWM to write and read back the module registers.

Due to synchronization issues, the HRPWM module clock frequency needs to be the same as the peripheral bus clock frequency ($f_{periph} < f_{ccu}$).

The peripheral bus clock frequency is controlled via the PBCLKCR.PBDIV field. The HRPWM module clock frequency is controlled via the CCUCLKCR.CCUDIV field. Both register are located in the SCU (System Control Unit).

Workaround

The peripheral bus clock and the module clock of the HRPWM need to have the same frequency ($f_{periph} = f_{ccu}$).

This is achieved by setting accordingly the following three fields:

- the CCUCLKCR.CCUDIV (field controlling the HRPWM and CCU4, CCU8 and POSIF peripherals module clock ratio);
- the CPUCLKCR.CPUDIV (field controlling the CPU clock division ratio);
- the PBCLKCR.PBDIV (field controlling the peripheral bus clock division ratio)

Table 6 shows the valid combinations for each of the previously mentioned fields. Notice that the frequency values given in the table are just an example (the real frequency would depend on the specific device and the PLL configuration).

Table 6 Valid Clock Combinations


Valid	CCUCLKCR.CCUDIV (frequency example)	CPUCLKCR.CPUDIV (frequency example)	PBCLKCR.PBDIV (frequency example)
Yes	0 (120 MHz)	0 (120 MHz)	0 (120 MHz)
No	0 (120 MHz)	0 (120 MHz)	1 (60 MHz)

Table 6 Valid Clock Combinations (cont'd)

Valid	CCUCLKCR.CCUDIV (frequency example)	CPUCLKCR.CPUDIV (frequency example)	PBCLKCR.PBDIV (frequency example)
No	0 (120 MHz)	1 (60 MHz)	0 (60 MHz)
Yes	1 (60 MHz)	0 (120 MHz)	1 (60 MHz)
Yes	1 (60 MHz)	1 (60 MHz)	0 (60 MHz)

LEDTS AI.001 Delay in the update of FNCTL.PADT bit field

The touch-sense pad turn (PADT) value is updated, not at the end of the touch-sense time slice (ColA), but one time slice later ([Figure 13](#)).


Figure 13 PADT update behavior

If the number of LED columns enabled is smaller than 2, the delay will affect the activation period of the current active pad. At the beginning of every new Col A, the value of the current PADT's compare register is updated to the internal compare register. However, the delay causes the value of the previous PADT's compare register is updated to the internal compare register instead. This means that the current active pad would be activated with the duration of the previous pad's oscillation window ([Figure 14](#)). In addition to this, when no LEDs

are enabled, pad turn 0 will prevail for one time slice longer before it gets updated ([Figure 15](#)).




Figure 14 Effect of delay on the update of Internal Compare Register with 1 LED column enabled




Figure 15 Pad turn 0 prevails for one time slice longer when no LEDs are enabled

If the number of LED columns enabled is 2 or more, the additional LED columns would provide some buffer time for the delay. So, at the start of a new touch-sense time slice, the update of PADT value would have taken place. Hence, the

current active PADT compare register value is updated to the internal compare register (**Figure 16**).




Figure 16 Internal Compare Register updated with correct compare register value with 2 LED columns enabled

Conditions

This delay in PADT update can be seen in cases where hardware pad turn control mode (FNCTL.PADTSW = 0) is selected and the touch-sense function is enabled (GLOBCTL.TS_EN = 1).

Workaround

This section is divided to two parts. The first part will provide a guide on reading the value of the bit field FNCTL.PADT via software. The second part will provide some workarounds for ensuring that the CMP_TS[x] values are aligned to the current active pad turn.

Workaround for reading PADT

Due to the delay in the PADT update, the user would get the current active pad turn when PADT is read in the time frame interrupt. However, this PADT value read differs when read in a time slice interrupt. This depends on the number of LED columns enabled and the active function or LED column in the previous

time slice ([Table 7](#)). The bit field FNCTL.FNCOL provides a way of interpreting the active function or LED column in the previous time slice.

Table 7 PADT value as read in the time slice interrupt

No. of LED Columns Enabled	Previous active function / LED column	FNCTL.FNCOL	PADT value
0-1	Touch-sense or LED Col0	110 _B or 111 _B	Previous active pad turn
2-7	Touch-sense or first LED column after touch-sense	110 _B or 111 _B	Previous active pad turn
	Second LED column after touch-sense onwards	101 _B to 000 _B	Current or next active pad turn

Workaround for aligning CMP_TSx

One workaround is to use the software pad turn control. Then this issue can be avoided entirely because the pad turn update will have to be handled by software.

However, it is still possible to work around this issue when using the hardware pad turn control. In the previous section, it is known that when the number of LED columns enabled is smaller than 2, the current active pad is activated with the oscillation window of the previous active pad. This means that the current active pad is activated with the value programmed in the bit field CMP_TS[x-1] instead of CMP_TS[x]. There are two possible software workarounds for this issue:

1. At the end of the time frame interrupt service routine, software can prepare for the next active pad turn by programming the CMP_TS[x-1] bit field with the intended compare value for TSIN[x]. As an example, if the next active pad is TSIN[2], program CMP_TS[1] with the compare value intended for TSIN[2] ([Figure 17](#)).




Figure 17 Software workaround demonstration

1. During the initialization phase, program the CMP_TS[x] bit fields with the left-shift factored in. Example: CMP_TS[0] for TSIN[1], CMP_TS[1] for TSIN[2], ... CMP[7] for TSIN[0].

PMU_CM.001 Branch from non-cacheable to cacheable address space instruction may corrupt the program execution

Two consecutive instruction fetch accesses, the first to the non-cacheable and the second to the cacheable address space may cause a corruption of the program flow. If the error occurs, the cached instruction at the target address is replaced with the opcode 0000_0000_H instead of the opcode of the correct instruction.

Conditions

One of the following cases may trigger the erroneous behavior:

1. In the normal program execution, a branch, function call or exception call operation, with the current instruction executed from the non-cacheable Flash address space and the branch target address in the cacheable Flash address space.
2. The CPU generates a speculative fetch access to the ROM address space when executing the BX LR instruction as an exception return to Thread mode and using the Process Stack Pointer (PSP), but not using the extended Floating-Point frame
(=> EXC_RETURN = FFFF_FFFD_H stored in the Link Register LR; LR can

be any GPR). This speculative access is followed by an access to the cacheable Flash address space (\Rightarrow the access to the actual branch target address).

Any of these cases results in two consecutive instruction fetch accesses in the code address space with

- the first an access to the non-cacheable Flash address space ($0C00_0000_H - 0C0F_FFFF_H$ or the ROM address space ($0000_0000_H - 0000_3FFF_H$))
- the second access in the cacheable Flash address space ($0800_0000_H - 080F_FFFF_H$), to be serviced from the Instruction Buffer, meaning the instruction is already stored in the Instruction Buffer of the Prefetch Unit (already executed before and not displaced/invalidated later in the program execution)

To see the problem from the normal program execution as described in the first case, the code allocation must be mixed, with some code segments allocated in the non-cacheable and other code segments in the cacheable address space. In such an environment code branches between the different segments, e.g. a function call from a cached thread to a function in the non-cacheable address space which then returns back to the cached thread, may trigger the problem.

In the second case, even if the complete application code is allocated in the cacheable Flash address space, the CPU may generate a speculative fetch access to the ROM address 0000_0000_H , triggered by the BX LR instruction and with $EXC_RETURN = FFFF_FFFD_H$, as described above in operation 2.

System considerations

- Only instruction fetches may trigger these accesses, data accesses are not affected.
- Instruction fetches to other address ranges than described above (e.g. PSRAM, DSRAM) are also not subject to the problem.
- The BX LR instruction can be used to return from regular functions and exception handlers alike. When the LR contains a regular address, the CPU will branch to that address. When LR contains a special EXC_RETURN code, the CPU does an exception return instead, reading the target address and restoring the processor status from the selected stack. The problem

occurs only with $\text{EXC_RETURN} = \text{FFFF_FFFD}_H$. Other system states result in different return codes, e.g. Handler mode instead of Thread mode, Floating Point state, or using the Main Stack Pointer use different EXC_RETURN codes. With any other EXC_RETURN code than FFFF_FFFD_H the CPU does not generate the speculative access to the address 0000_0000_H , thus not generating the critical access sequence of a non-cacheable access that is followed by a cacheable access.

Workaround

Allocate the complete code either in the cacheable or non-cacheable Flash address space, do not use mixed code allocation. This workaround covers all accesses out of the normal program flow. Equivalent to the allocation in the non-cacheable address space with respect to reduced execution performance, it is also possible to disable the Instruction Buffer with PREF_PCON.IBYP .

If the code is allocated in the cacheable Flash address space, the BX LR instruction must not be executed with the exception return code $\text{LR} = \text{FFFF_FFFD}_H$.

It is possible to replace the BX LR instruction with the following sequence:

1. PUSH LR
2. POP PC

This sequence does not generate the speculative ROM access, thus it does not generate the critical access sequence of a non-cacheable access that is followed by a cacheable access.

If the application allows, the critical exception return code of the BX LR instruction can be avoided by operating in different CPU state, e.g. if the application does not use the Process Stack Pointer.

PORTS CM.002 P0.9 Pull-up permanently active

A pull-up device on P0.9 is permanently active, disregarding any PORTS or peripheral configurations.

This is not the standard pull device under control of the PORTS, but it is $R_{\text{UID_PU}}$, a part of the USB device detection circuitry of the USB.ID function, mapped to P0.9. Its characteristic resistance is documented in the Data Sheet.

Implications

This pull device may have adverse effects on currents drawn or driven, as well as signal slopes and timings of the connected interfaces.

Workaround

None.

PORTS CM.005 Different PORT register reset values after module reset

The PORTS registers can be reset independent of the reset of the system with SCU_PRSET1.PPORTSRS. After such a module reset, some PORTS registers have a reset value different to the reset value that is documented in the Reference Manual.

Table 8 PORTS registers reset values

Register	Sytem reset value	Module reset value
Pn_IOC8	0000 0000 _H	2020 2020 _H ¹⁾
Pn_PDISC	XXXX XXXX _H ²⁾	0000 0000 _H
Pn_PDR0	2222 2222 _H	0000 0000 _H
Pn_PDR1	2222 2222 _H	0000 0000 _H

1) Only in XMC4500 devices.

2) Device and package dependent

Implications

The different value in Pn_IOC8 configures the respective port pins Pn.[11:8] as inverted inputs instead of direct inputs. User software in Priviledged Mode can reconfigure them as needed by the application.

With the different value in Pn_PDISC of the digital ports the availability of digital pins in a device can no longer be verified via this register. Note that Pn_PDISC of pure digital ports is read-only; user software can't write to them.

The Pn_PDISC of the shared analog/digital port pins (P14 and P15) enables/disables the digital input path. After a system reset this path is

disabled, after a module reset enabled. User software in Priviledged Mode can reconfigure them as needed by the application.

The different value in the Pn_PDR registers configures output port pins with a “Strong-Sharp” output driver mode, as opposed to “Strong-Soft” driver mode after a system reset. This may result in a higher current consumption and more noise induced to the external system. User software in Priviledged Mode can reconfigure them as needed by the application.

Workaround

None.

POSIF AI.001 Input Index signal from Rotary Encoder is not decoded when the length is 1/4 of the tick period

Each POSIF module can be used as an input interface for a Rotary Encoder. It is possible to configure the POSIF module to decode 3 different signals: Phase A, Phase B (these two signals are 90° out of phase) and Index. The index signal is normally understood as the marker for the zero position of the motor Figure 1.




Figure 18 Rotary Encoder outputs - Phase A, Phase B and Index

There are several types of Rotary Encoder when it comes to length of the index signal:

- length equal or bigger than 1 tick period
- length equal or bigger than 1/2 tick period

- length equal or bigger than 1/4 tick period

When the index signal is smaller than 1/2 of the tick period, the POSIF module is not able to decode this signal properly, Figure 2 - notice that the reference edge of the index generation in this figure is the falling of Phase B, nevertheless this is an example and depending on the encoder type, this edge may be one of the other three.

Due to this fact it is not possible to use the POSIF to decode these type of signals (index with duration below 1/2 of the tick period).




Figure 19 Different index signal types

Workaround

To make usage of the Index signal, when the length of this signal is less than 1/2 of the tick period, one should connect it directly to the specific counter/timer. This connection should be done at port level of the device (e.g. connecting the device port to the specific Timer/Counter(s)), Figure 3.




Figure 20 Index usage workaround - a) Non working solution; b) Working solution

SCU CM.006 Deep sleep entry with PLL power-down option generates SOSCWDGT and SVCOLCKT trap

Entering the deep sleep mode with PLL power-down option (selected in DSLEEPCCR register of SCU module) may result with system traps triggered by PLL watchdog (the SOSCWDGT trap) and/or loss-of-lock (the SVCOLCKT trap).

Implications

Occurrence of one of the enabled traps will result in an immediate wake-up from the deep sleep state, i.e. the deep sleep is effectively not entered.

Workaround

Disable SOSCWDGT and SVCOLCKT trap generation in TRAPDIS register of SCU before entering deep sleep mode with PLL power-down option selected.

SCU_CM.015 Parity Memory Test function not usable

The device provides an interface to access the parity bits of the contained memories. The interface is based on using SCU registers PMTPR and PMTSR. Due to synchronization issues wrong results will be produced.

Implications

The Parity Memory Test function is not usable.

Workaround

None.

STARTUP_CM.001 CAN Bootstrap Loader

The oscillator start up detection by device firmware does not check for a required stable frequency lock. Therefore is not possible to support an entire spectrum of standard XTAL input frequencies in the CAN BSL boot mode. As a result the device may not answer the initial CAN frame.

Workaround

None.

USIC_AI.008 SSC delay compensation feature cannot be used

SSC master mode and complete closed loop delay compensation cannot be used. The bit DX1CR.DCEN should always be written with zero to disable the delay compensation.

Workaround

None.

USIC AI.010 Minimum and maximum supported word and frame length in multi-IO SSC modes

The minimum and maximum supported word and frame length in multi-IO SSC modes are shown in the table below:

Table 9

Multi-IO SSC Modes	Word Length (bits)		Frame Length (bits)	
	Minimum	Maximum	Minimum	Maximum
Dual-SSC	4	16	4	64
Quad-SSC	8	16	8	64

Workaround

If a frame length greater than 64 data bits is required, the generation of the master slave select signal by SSC should be disabled by PCR.MLSSEN.

To generate the master slave select signal:

- Configure the same pin (containing the SELOx function) to general purpose output function instead by writing 10000_B to the pin's input/output control register (Pn_IOCRx.PCy); and
- Use software to control the output level to emulate the master slave select signal

This way, multiple frames of 64 data bits can be made to appear as a single much larger frame.

USIC AI.013 SCTR register bit fields DSM and HPCDIR are not shadowed with start of data word transfer

The bit fields DSM and HPCDIR in register SCTR are not shadowed with the start of a data word transfer.

Workaround

If the transfer parameters controlled by these bit fields need to be changed for the next data word, they should be updated only after the current data word transfer is completed, as indicated by the transmit shift interrupt PSR.TSIF.

USIC AI.014 No serial transfer possible while running capture mode timer

When the capture mode timer of the baud rate generator is enabled (BRG.TMEN = 1) to perform timing measurements, no serial transmission or reception can take place.

Workaround

None.

USIC AI.015 Wrong generation of FIFO standard transmit/receive buffer events when TBCTR.STBTEN/RBCTR.SRBTEN = 1

Transmit FIFO buffer modes selected by TBCTR.STBTEN = 1 generates a standard transmit buffer event whenever TBUF is loaded with the FIFO data or there is a write to INxx register, except when TRBSR.TBFLVL = TBCTR.LIMIT. This is independent of TBCTR.LOF setting.

Similarly, receive FIFO buffer modes selected by RBCTR.SRBTEN = 1 generates a standard receive buffer event whenever data is read out from FIFO or received into the FIFO, except when TRBSR.RBFLVL = RBCTR.LIMIT. This is independent of RBCTR.LOF setting.

Both cases result in the wrong generation of the standard transmit and receive buffer events and interrupts, if interrupts are enabled.

Workaround

Use only the modes with TBCTR.STBTEN and RBCTR.SRBTEN = 0.

USIC AI.016 Transmit parameters are updated during FIFO buffer bypass

Transmit Control Information (TCI) can be transferred from the bypass structure to the USIC channel when a bypass data is loaded into TBUF. Depending on the setting of TCSR register bit fields, different transmit parameters are updated by TCI:

Functional Deviations

- When SELMD = 1, PCR.CTR[20:16] is updated by BYPCR.SELO (applicable only in SSC mode)
- When WLEMD = 1, SCTR.WLE and TCSR.EOF are updated by BYPCR.BWLE
- When FLEMD = 1, SCTR.FLE[4:0] is updated by BYPCR.BWLE
- When HPCMD = 1, SCTR.HPCDIR and SCTR.DSM are updated by BHPC
- When all of the xxMD bits are 0, no transmit parameters will be updated

However in the current device, independent of the xxMD bits setting, the following are always updated by the TCI generated by the bypass structure, when TBUF is loaded with a bypass data:

- WLE, HPCDIR and DSM bits in SCTR register
- EOF and SOF bits in TCSR register
- PCR.CTR[20:16] (applicable only in SSC mode)

Workaround

The application must take into consideration the above behaviour when using FIFO buffer bypass.

USIC_AI.017 Clock phase of data shift in SSC slave cannot be changed

Setting PCR.SLPHSEL bit to 1 in SSC slave mode is intended to change the clock phase of the data shift such that reception of data bits is done on the leading SCLKIN clock edge and transmission on the other (trailing) edge.

However, in the current implementation, the feature is not working.

Workaround

None.

USIC_AI.018 Clearing PSR.MSLS bit immediately deasserts the SELOx output signal

In SSC master mode, the transmission of a data frame can be stopped explicitly by clearing bit PSR.MSLS, which is achieved by writing a 1 to the related bit position in register PSCR.

Functional Deviations

This write action immediately clears bit PSR.MSLS and will deassert the slave select output signal SELOx after finishing a currently running word transfer and respecting the slave select trailing delay (T_{td}) and next-frame delay (T_{nf}).

However in the current implementation, the running word transfer will also be immediately stopped and the SELOx deasserted following the slave select delays.

If the write to register PSCR occurs during the duration of the slave select leading delay (T_{ld}) before the start of a new word transmission, no data will be transmitted and the SELOx gets deasserted following T_{td} and T_{nf} .

Workaround

There are two possible workarounds:

- Use alternative end-of-frame control mechanisms, for example, end-of-frame indication with TSCR.EOF bit.
- Check that any running word transfer is completed (PSR.TSIF flag = 1) before clearing bit PSR.MSLS.

USIC AI.019 First data word received by IIC receiver triggers RIF instead of AIF

When operating in IIC mode as a master or slave receiver, the first data word received following a start condition and address match triggers a receive event (indicated by PSR.RIF flag) instead of an alternate receive event (indicated by PSR.AIF flag).

Workaround

To determine if a received data word is the first word of a new frame, bit 9 of RBUF needs to be read:

- When RBUF[9] is 1, the first data word of a new frame is indicated;
- When RBUF[9] is 0, subsequent data words of the frame are indicated.

USIC AI.020 Handling unused DOUT lines in multi-IO SSC mode

In multi-IO SSC mode, when the number of DOUT lines enabled through the bit field CCR.HPCEN is greater than the number of DOUT lines used as defined in the bit field SCTR.DSM, the unused DOUT lines output incorrect values instead of the passive data level defined by SCTR.PDL.

Implications

Unintended edges on the unused DOUT lines.

Workaround

To avoid unintended edges on the unused DOUT lines, it is recommended to use the exact number of DOUT lines as enabled by the hardware controlled interface during a multi-IO data transfer.

3 Application Hints

The errata in this section describe application hints which must be regarded to ensure correct operation under specific application conditions.

ADC AI.H004 Completion of Startup Calibration

Before using the VADC the startup calibration must be completed.

The calibration is started by setting GLOBCFG.SUCAL. The active phase of the calibration is indicated by GxARBCFG.CAL = 1. Completion of the calibration is indicated by GxARBCFG.CAL = 0.

When checking for bit CAL = 1 immediately after setting bit SUCAL, bit CAL might not yet be set by hardware. As a consequence the active calibration phase may not be detected by software. The software may use the following sequence for startup calibration:

1. GLOBCFG.SUCAL = 1
2. Wait for GxARBCFG.CAL = 1
3. Check for GxARBCFG.CAL = 0 before starting a conversion

Make sure that steps 1 and 2 of this sequence are not interrupted to avoid a deadlock situation with waiting for GxARBCFG.CAL = 1.

ADC TC.H011 Bit DCMSB in register GLOBCFG

The default setting for bit DCMSB (Double Clock for the MSB Conversion) in register GLOBCFG is 0_B, i.e. one clock cycle for the MSB conversion step is selected.

DCMSB = 1_B is reserved in future documentation and must not be used.

MultiCAN AI.H005 TxD Pulse upon short disable request

If a CAN disable request is set and then canceled in a very short time (one bit time or less) then a dominant transmit pulse may be generated by MultiCAN module, even if the CAN bus is in the idle state.

Example for setup of the CAN disable request:

Workaround

Set all INIT bits to 1 before requesting module disable.

MultiCAN AI.H006 Time stamp influenced by resynchronization

The time stamp measurement feature is not based on an absolute time measurement, but on actual CAN bit times which are subject to the CAN resynchronization during CAN bus operation. The time stamp value merely indicates the number of elapsed actual bit times. Those actual bit times can be shorter or longer than nominal bit time length due to the CAN resynchronization events.

Workaround

None.

MultiCAN AI.H007 Alert Interrupt Behavior in case of Bus-Off

The MultiCAN module shows the following behavior in case of a bus-off status:




Figure 21 Alert Interrupt Behavior in case of Bus-Off

When the threshold for error warning (EWRN) is reached (default value of Error Warning Level EWRN = 0x60), then the EWRN interrupt is issued. The bus-off (BOFF) status is reached if $TEC > 255$ according to CAN specification, changing the MultiCAN module with REC and TEC to the same value 0x1, setting the INIT bit to 1_B, and issuing the BOFF interrupt. The bus-off recovery phase starts automatically. Every time an idle time is seen, REC is incremented.

If REC = 0x60, a combined status EWRN+BOFF is reached. The corresponding interrupt can also be seen as a pre-warning interrupt, that the bus-off recovery phase will be finished soon. When the bus-off recovery phase has finished (128 times idle time have been seen on the bus), EWRN and BOFF are cleared, the ALERT interrupt bit is set and the INIT bit is still set.

MultiCAN AI.H008 Effect of CANDIS on SUSACK

When a CAN node is disabled by setting bit NCR.CANDIS = 1_B, the node waits for the bus idle state and then sets bit NSR.SUSACK = 1_B.

However, SUSACK has no effect on applications, as its original intention is to have an indication that the suspend mode of the node is reached during debugging.

MultiCAN TC.H003 Message may be discarded before transmission in STT mode

If MOFCRn.STT=1 (Single Transmit Trial enabled), bit TXRQ is cleared (TXRQ=0) as soon as the message object has been selected for transmission and, in case of error, no retransmission takes places.

Therefore, if the error occurs between the selection for transmission and the real start of frame transmission, the message is actually never sent.

Workaround

In case the transmission shall be guaranteed, it is not suitable to use the STT mode. In this case, MOFCRn.STT shall be 0.

MultiCAN TC.H004 Double remote request

Assume the following scenario: A first remote frame (dedicated to a message object) has been received. It performs a transmit setup (TXRQ is set) with clearing NEWDAT. MultiCAN starts to send the receiver message object (data

frame), but loses arbitration against a second remote request received by the same message object as the first one (**NEWDAT** will be set).

When the appropriate message object (data frame) triggered by the first remote frame wins the arbitration, it will be sent out and **NEWDAT** is not reset. This leads to an additional data frame, that will be sent by this message object (clearing **NEWDAT**).

There will, however, not be more data frames than there are corresponding remote requests.




Figure 22 Loss of Arbitration

RESET CM.H001 Power-On Reset Release

The on-chip EVR implements a power validation circuitry which supervises VDDP and VDDC. This circuit releases or asserts the system reset to ensure safe operation. This reset is visible on bidirectional $\overline{\text{PORST}}$ pin.

Implications

Potential effects if the $\overline{\text{PORST}}$ release requirement is not met (please refer to the Data Sheet for details) is presence of spikes or toggling on the $\overline{\text{PORST}}$ pin which may have an effect on the rest of the system if the reset signal is shared with other electronic components on the PCB. A repeated $\overline{\text{PORST}}$ may also result in loss of information about hibernation status after an interrupted wake-

up has been performed. Potential presence of the spikes on $\overline{\text{PORST}}$, however, will not lead to a fatal system startup failure or deadlock.

Recommendation

It is required to ensure fast $\overline{\text{PORST}}$ release, as specified in Data Sheet. The recommended approach is to apply a pull-up resistor on the $\overline{\text{PORST}}$ pin.

Typically a 10 - 90 k Ω resistor is sufficient in application cases where the device is in control of the reset generation performed by its internal power validation circuit and no additional load is applied to the $\overline{\text{PORST}}$ pin. The required pull-up resistor value may vary depending on the electrical parameters of the system, like parasitic wire resistance and capacitance of the PCB, driving strength of other electronic components connected to the $\overline{\text{PORST}}$ pin and other side conditions. The pull-up resistance may need to be adapted accordingly.