

# Errata Sheet

July 7, 2003 / Release 1.2

<b>Device:</b>	<b>SAK-C167CS-LM SAK-C167CS-L33M SAK-C167CS-L40M SAK-C167CS-4RM SAK-C167CS-4R33M SAK-C167CS-4R40M</b>
<b>Stepping Code / Marking:</b>	<b>ES-BA, BA, BA 6</b>
<b>Package:</b>	<b>P-MQFP-144-1, P-MQFP-144-6 (BA 6)</b>

This Errata Sheet describes the deviations from the current user documentation. The classification and numbering system is module oriented in a continual ascending sequence over several derivatives, as well already solved deviations are included. So gaps inside this enumeration could occur.

The current documentation is: Data Sheet: C167CS Data Sheet V2.2 2001-08  
User's Manual: C167CS User's Manual V2.0 2000-07  
Instruction Set Manual V2.0, 2001-03

**Note: Devices marked with EES or ES are engineering samples which may not be completely tested in all functional and electrical characteristics, therefore they should be used for evaluation only.**

The specific test conditions for EES and ES are documented in a separate Status Sheet.

**Change summary to Errata Sheet Rel.1.1 for C167CS-4RM/LM devices with stepping code/marking ES-BA, BA:**

- Z Flag after PUSH and PCALL (CPU.22)
- Note on Early (Unlatched) Chip Select Option (Section Application Hints)
- Note and Link to Oscillator Application Note AP2420 updated (Section Functional Improvements/Documentation Updates)

## Functional Problems:

### **PWRDN.1: Execution of PWRDN Instruction while pin NMI# = high**

When instruction PWRDN is executed while pin NMI# is at a high level, power down mode should not be entered, and the PWRDN instruction should be ignored. However, under the conditions described below, the PWRDN instruction may not be ignored, and no further instructions are fetched from external memory, i.e. the CPU is in a quasi-idle state. This problem will only occur in the following situations:

- a) the instructions following the PWRDN instruction are located in external memory, and a **multiplexed bus configuration with memory tristate waitstate** (bit MTTCx = 0) is used, or
- b) the instruction preceding the PWRDN instruction **writes** to external memory or an XPeripheral (XRAM, CAN), and the instructions following the PWRDN instruction are located in external memory. In this case, the problem will occur for any bus configuration.

**Note:** the on-chip peripherals are still working correctly, in particular the Watchdog Timer will reset the device upon an overflow. Interrupts and PEC transfers, however, can not be processed. In case NMI# is asserted low while the device is in this quasi-idle state, power down mode is entered.

### **Workaround:**

Ensure that no instruction which writes to external memory or an XPeripheral precedes the PWRDN instruction, otherwise insert e.g. a NOP instruction in front of PWRDN. When a multiplexed bus with memory tristate waitstate is used, the PWRDN instruction should be executed out of internal RAM or XRAM.

### **ADC.11: Modifications of ADM field while bit ADST = 0**

The A/D converter may unintentionally start one auto scan single conversion sequence when the following sequence of conditions is true:

- (1) the A/D converter has finished a fixed channel single conversion of an analog channel  $n > 0$  (i.e. contents of ADCON.ADCH =  $n$  during this conversion)
- (2) the A/D converter is idle (i.e. ADBSY = 0)
- (3) then the conversion mode in the ADC Mode Selection field ADM is changed to Auto Scan Single (ADM = 10b) or Continuous (ADM = 11b) mode without setting bit ADST = 1 with the same instruction

Under these conditions, the A/D converter will unintentionally start one auto scan single conversion sequence, beginning with channel  $n-1$ , down to channel number 0.

In case the channel number ADCH has been changed before or with the same instruction which selected the auto scan mode, this channel number has no effect on the unintended auto scan sequence (i.e. it is not used in this auto scan sequence).

### **Note:**

When a conversion is already in progress, and then the configuration in register ADCON is changed,

- the new conversion mode in ADM is evaluated after the current conversion
- the new channel number in ADCH and new status of bit ADST are evaluated after the current conversion when a conversion in fixed channel conversion mode is in progress, and after the current conversion sequence (i.e. after conversion of channel 0) when a conversion in an auto scan mode is in progress.

In this case, it is a specified operational behaviour that channels  $n-1$  .. 0 are converted when ADM is changed to an auto scan mode while a fixed channel conversion of channel  $n$  is in progress (see e.g. C167CS User's Manual, V2.0, p18-6)

### **Workaround:**

When an auto scan conversion is to be performed, always start the A/D converter with the same instruction which sets the configuration in register ADCON.

### **CAPCOM.4: SW Access to P1H Overwrites CAPCOM HW Settings**

HW settings on P1H.7...4 by CAPCOM compare output functions (CC24 ... CC27) can be overwritten by SW accesses to P1H.7...0 on the same port.

Read modify write operations like BSET, BFLDx, OR, ... read the input or output latches respectively, modify the affected bits and write back the result to the output latches of the whole port (P1H7...0).

In case a compare event has occurred after the read phase, but before the write-back phase of such an instruction, the output signal change of the compare event is lost or only a short pulse ( $\geq 1$  TCL) may appear. The bit protection mechanism to avoid these effects is out of function on P1H.

### **Workarounds:**

1. Avoid the combination of HW and SW write accesses to P1H. HW access only to CC24 ... CC27 or SW access only to P1H.7 ... 0 works properly.
2. Use „interrupt only“ compare modes (CCMODx = 100 or 110) and modify the port pin in the interrupt service routine by software to avoid the combination of HW and SW accesses.

### **RST.15.2: New Behaviour: Software/Watchdog/Short HW Reset during Slow Down operation with PLL off**

When a watchdog timer or software reset or short HW reset occurs during slow down mode where the PLL has been switched off (CLKCON = 10 in register SYSCON2), the internal reset condition is extended until the next long HW reset.

After the reset, if the PLL has not locked, flag PLLIR in register ISNC **is correctly set and** the device continues operation on the PLL base frequency (2 .. 5 MHz). Flag PLLIR in register ISNC can be used to check the clock source: if PLLIR = 1, the PLL base frequency (2 .. 5 MHz) is used instead of the frequency derived from the oscillator input XTAL1.

This problem only occurs when the PLL is used to generate the internal clock during normal operation, and it will not occur in direct drive or prescaler mode.

### **Workaround:**

Enable bi-directional reset mode (bit BDRSTEN = 1 in register SYSCON). The external reset circuit should prolong this reset until the PLL is locked again (approx. 1 ms).

### **X9: Read Access to XPERs in Visible Mode**

The data of a read access to an XBUS-Peripheral (XRAM, CAN) in Visible Mode is not driven to the external bus. PORT0 is tristated during such read accesses.

Note that in Visible Mode PORT1 will drive the address for an access to an XBUS-Peripheral, even when only a multiplexed external bus is enabled.

### **X17: XBUS Access after External Access with EWEN = 1 and/or BSWC = 1**

1. When the last external bus access which precedes an internal XBUS-Peripheral access is performed with bit **BUSCONx.11/BSWCx = 1 (BUSCON Switch Tristate Waitstate)**, the XBUS cycle will be performed without BUSCON Switch Tristate Waitstate, and the BUSCON Switch Tristate Waitstate will be inserted at the beginning of the next external bus cycle.

**Workaround:** the data of an internal XBUS write cycle will be driven on Port 0 starting 2 TCL after the rising edge of ALE. In case the tdf (output disable time) specification of the external device does not meet the following requirements

tdf < 4 TCL – 15 + tf [ns] for a multiplexed bus cycle via BUSCONx, or

tdf < 2 TCL – 15 + tf [ns] for a non-multiplexed bus cycle via BUSCONx,

then use a standard Memory Tristate Time Waitstate instead of a BUSCON Switch Tristate Waitstate, i.e. set bit BUSCONx.5/MTTCx = 0.

2. When the last external bus access which precedes an internal XBUS-Peripheral access is performed with bit **BUSCONx.8/EWENx = 1 (Early Write)**, the XBUS cycle will also be performed with 'Early Write'.

**Workaround:** not required, internal XBUS-Peripherals tolerate write accesses with Early Write.

### **POWER.15: Sleep Mode not possible in Prescaler Mode**

In prescaler mode ( $f_{CPU} = f_{OSC}/2$ ) instead of sleep the device enters an undefined state and no wake up is possible except HW reset.

#### **Workaround:**

Avoid sleep mode with prescaler mode (use deep idle instead: all peripherals off and slow down divider/32 and idle mode)

## **CPU.21 BFLDL/BFLDH Instructions after Write Operations to internal IRAM**

The result of a BFLDL/BFLDH (=BFLDx) instruction may be incorrect if the following conditions are true at the same time:

- (1) the previous 'instruction' is a PEC transfer which writes to IRAM, or any instruction with result write back to IRAM (addresses 0F200h..0FDFFh for 3 Kbyte module, 0F600h..0FDFFh for 2 Kbyte module, or 0FA00h..0FDFFh for 1 Kbyte module). For further restrictions on the destination address see case (a) or case (b) below.
- (2) the BFLDx instruction immediately follows the previous instruction or PEC transfer within the instruction pipeline ('back-to-back' execution), i.e. decode phase of BFLDx and execute phase of the previous instruction or PEC transfer coincide. This situation typically occurs during program execution from internal program memory (ROM/OTP/Flash), or when the instruction queue is full during program execution from external memory
- (3) the 3<sup>rd</sup> byte of BFLDx (= **#mask8** field of BFLDL or **#data8** field of BFLDH) and the destination address of the previous instruction or PEC transfer match in the following way:
  - (a) value of #mask8 of BFLDL or #data8 of BFLDH = 0Fyh (**y** = 0..Fh),  
**and** the previous instruction or PEC writes to (the low and/or high byte of) GPR Ry or the memory address of Ry (determined by the context pointer CP) via any addressing mode.
  - (b) value of #mask8 of BFLDL or #data8 of BFLDH = 00h..0EFh,  
**and** the lower byte  $v_L$  of the **contents v** of the IRAM location or (E)SFR or GPR which is read by BFLDx is  $00h \leq v_L \leq 7Fh$   
**and** the previous instruction or PEC transfer writes to the (low and/or high byte of) the specific bit-addressable IRAM location **0FD00h + 2  $v_L$**  (i.e. the 8-bit offset address of the location in the bit-addressable IRAM area (0FD00h..0FDFFh) equals  $v_L$ ).

When the problem occurs, the actual result (all 16 bits) of the BFLDx instruction is bitwise ORed with the (byte or word) result of the previous instruction or PEC transfer.

### **Notes:**

Write operations in the sense of the problem description include implicit write accesses caused by

- auto-increment operations of the PEC source or destination pointers (which are located on 0FCE0h..0FCFEh in IRAM)
- post-increment/pre-decrement operations on GPRs (addressing modes with [R+] or [-R])
- write operations on the system stack (which is located in IRAM).

In case **PEC write operations** to IRAM locations which match the above criteria (bit-addressable or active register bank area, PEC pointers not overlapping with register bank area) can be **excluded**, the problem will **not** occur when the instruction preceding BFLDx in the dynamic flow of the program is one of the following instructions (which do not write to IRAM):

NOP  
ATOMIC, EXTx  
CALLA/CALLI/JBC/JNBS when branch condition = false  
JMPx, JB, JNB  
RETx (except RETP)  
CMP(B) (except addressing mode with [Rwi+]), BCMP  
MULx, DIVx  
IDLE, PWRDN, DISWDT, SRVWDT, EINIT, SRST

For implicit IRAM write operations caused by **auto-increment operations of the PEC source or destination pointers**, the problem can only occur if the value of #mask8 of BFLDL or #data8 of BFLDH = 0Fyh (**y** = 0..Fh), and the range which is covered by the context pointer CP (partially or completely) overlaps the PEC source and destination pointer area (0FCE0h..0FCFEh), and the address of the source or destination pointer which is auto-incremented after the PEC transfer is equal to the address of GPR Ry (included in case 3a).

For **system stack write operations**, the problem can only occur if the system stack is located in the bit-addressable portion of IRAM (0FD00h..0FDFFh), or if the system stack can overlap the register bank area (i.e. the register bank area is located below the system stack, and the distance between the contents of the context pointer CP and the stack pointer SP is  $\leq 20h$ ).

**Workaround 1:**

When a critical instruction combination or PEC transfer to IRAM can occur, then substitute the BFLDx instruction by

- (a) an equivalent sequence of single bit instructions. This sequence may be included in an uninteruptable ATOMIC or EXTEND sequence to ensure completion after a defined time.
- (b) an equivalent byte- or word MOV or logical instruction.

Note that byte operations to SFRs always clear the non-addressed complementary byte.  
 Note that protected bits in SFRs are overwritten by MOV or logical instructions.

**Workaround 2:**

When a critical instruction combination occurs, and **PEC write operations** to IRAM locations which match the above criteria (bit-addressable or active register bank area) **can be excluded**, then rearrange the BFLDx instruction within the instruction environment such that a non-critical instruction sequence is generated.

**Workaround 3:**

When a critical instruction combination or PEC transfer to IRAM can occur, then

- replace the BFLDx instruction by the instruction sequence  
     ATOMIC #1  
     BFLDx

This means e.g. when BFLDx was a branch target before, ATOMIC # 1 is now the new branch target.

In case the BFLDx instruction is included at position **n** in an ATOMIC or EXTEND sequence with range operator **#m** ( $n, m = 2..4, n \leq m$ ), then

- insert (repeat) the corresponding ATOMIC or EXTEND instruction at position **n** with range operator **#z** where  $z = (m - n) + 1$

Position of BFLDx within ATOMIC/EXT.. sequence	Range of original ATOMIC/EXTEND statement			
	1	2	3	4
1	no problem / no workaround	no problem / no workaround	no problem / no workaround	no problem / no workaround
2	--	z = 1	z = 2	z = 3
3	--	--	z = 1	z = 2
4	--	--	--	z = 1

-- : case can not occur

## Tool Support for Problem CPU.21

The **Keil C166 Compiler V3.xx** generates BFLD instructions only in the following cases:

- when using the `_bfld_` intrinsic function.
- at the beginning of interrupt service routines, when using `#pragma disable`
- at the end of interrupt service routines, when using the chip bypass directive `FIX166`.

The C166 Compiler V4.xx uses the BFLD instruction to optimize bit-field struct accesses. Release C166 V4.10 offers a new directive called `FIXBFLD` that inserts an `ATOMIC #1` instruction before every BFLD instruction that is not enclosed in an `EXTR` sequence. Detailed information can be found in the `C166\HLP\RELEASE.TXT` of C166 Version 4.10.

The C166 Run-Time Library for C166 V3.xx and V4.xx uses BFLD instructions only in the `START167.A66` file. This part of the code should be not affected by the CPU.21 problem but should be checked by the software designer.

The RTX166 Full Real-Time Operating system (any version) does not use BFLD instructions. For RTX166 Tiny, you should rebuild the RTX166 Tiny library with the `SET FIXBFLD = 1` directive. This directive is enabled in the assembler source file `RTX166T.A66`. After change of this setting rebuild the RTX166 Tiny library that you are using in your application.

The **Tasking** support organization provides a v7.0r1 A166 Assembler (build 177) including a check for problem CPU.21 with optional `pec/no_pec` feature. This assembler version can also be used to check code which was generated with previous versions of the Tasking tool chain. A v7.0r1 C166 Compiler (build 368) offering a workaround for problem CPU.21 is also available from Tasking.

The scan tool **aiScan21** analyzes files in hex format plus user-supplied additional information (locator map file, configuration file), checks whether they may be affected by problem CPU.21, and produces diagnostic information about potentially critical instruction sequences. This tool is included in AP1628 'Scanning for Problem CPU.21' on

[http://www.infineon.com/cgi/ecrm.dll/ecrm/scripts/prod\\_cat.jsp?oid=-8137](http://www.infineon.com/cgi/ecrm.dll/ecrm/scripts/prod_cat.jsp?oid=-8137)

## **CPU.22: Z Flag after PUSH and PCALL**

The Z flag in the PSW is erroneously set to '1' by ***PUSH reg*** or ***PCALL reg, rel*** instructions when all of the following conditions are true:

(a) for ***PUSH reg*** instructions:

- the contents of the high byte of the GPR or (E)SFR which is pushed is 00h, and
- the contents of the low byte of the GPR or (E)SFR which is pushed is > 00h, and
- the contents of GPR Rx is odd, where x = 4 msbs of the 8-bit 'reg' address of the pushed GPR or (E)SFR

Examples:

`PUSH R1` (coding: **F1 EC**): incorrect setting of Z flag if contents of **R15** is odd, and `00FFh` ≥ contents of **R1** ≥ `0001h`

`PUSH DPP3` (coding: **03 EC**): incorrect setting of Z flag if contents of **R0** is odd, and `00FFh` ≥ contents of **DPP3** ≥ `0001h`

(b) for ***PCALL reg, rel*** instructions:

- when the contents of the high byte of the GPR or (E)SFR which is pushed is 00h, and
- when the contents of the low byte of the GPR or (E)SFR which is pushed is odd

This may lead to wrong results of instructions following PUSH or PCALL if those instructions explicitly (e.g. BMOV .., Z; JB Z, ..; ..) or implicitly (e.g. JMP cc\_Z, ..; JMP cc\_NET, ..; ..) evaluate the status of the Z flag before it is newly updated.

Note that some instructions (e.g. CALL, ..) have no effect on the status flags, such that the status of the Z flag remains incorrect after a PUSH/PCALL instruction until an instruction that correctly updates the Z flag is executed.

```
Example:
PUSH R1          ; incorrect setting of Z flag if R15 is odd
CALL proc_xyz   ; Z flag remains unchanged (is a parameter for proc_xyz)
...
proc_xyz:
JMP cc_Z,end_xyz ; Z flag evaluated with incorrect setting
...
end_xyz:
```

### Effect on Tools:

The **Hightec** C166 tools (all versions) don't use the combination of PUSH/PCALL and the evaluation of the Z flag. Therefore, these tools are not affected.

The code generated by the **Keil** C166 Compiler evaluates the Z flag only after MOV, CMP, arithmetic, or logical instructions. It is never evaluated after a PUSH instruction. PCALL instructions are not generated by the C166 Compiler.

This has been checked with all C166 V3.xx and V4.xx compiler versions. Even the upcoming V5.xx is not affected by the CPU.22 problem.

The assembler portions of the C166 V3.xx and V4.xx Run-Time Libraries, the RTX166 Full and TX166 Tiny Real Time Operating system do also not contain any evaluation of the Z flag after PUSH or PCALL.

The **TASKING** compiler V7.5r2 never generates a PCALL instruction, nor is it used in the libraries. The PUSH instruction is only used in the entry of an interrupt frame, and sometimes on exit of normal functions. The zero flag is not a parameter or return value, so this does not give any problems.

Previous versions of TASKING tools: V3.x and higher are not affected, versions before 3.x are most likely not affected. Contact TASKING when using versions before V3.x.

Since code generated by the C166 **compiler** versions mentioned before is **not** affected, analysis and workarounds are **only** required for program parts written in **assembler**, or instruction sequences inserted via inline assembly.

### Workaround (for program parts written in assembler):

Do not evaluate the status of the Z flag generated by a PUSH or PCALL instruction. Instead, insert an instruction that correctly updates the PSW flags, e.g.

```
PUSH reg
CMP reg, #0          ; updates PSW flags
                    ; note: CMP additionally modifies the C and V flags,
                    ; while PUSH or MOV leaves them unaffected
JMPR cc_Z, label_1  ; implicitly tests Z flag

or
PCALL reg, procedure_1
```

```

...
procedure_1:
    MOV ONES, reg          ; updates PSW flags
    JMPR cc_NET, label_1 ; implicitly tests flags Z and E

```

## Hints for Detection of Critical Instruction Combinations

Whether or not an instruction following *PUSH reg* or *PCALL reg, rel* actually causes a problem depends on the program context. In most cases, it will be sufficient to just analyze the instruction following PUSH or PCALL. In case of PCALL, this is the instruction at the call target address.

### - Support Tool for Analysis of Hex Files

For complex software projects, where a large number of assembler source (or list) files would have to be analyzed, Infineon provides a tool **aiScan22** which scans hex files for critical instruction sequences and outputs diagnostic information. This tool is available as part of the Application Note **ap1679** 'Scanning for Problem CPU.22' on the 16-bit microcontroller internet pages of Infineon Technologies: [http://www.infineon.com/cgi/ecrm.dll/ecrm/scripts/prod\\_cat.jsp?oid=-8137](http://www.infineon.com/cgi/ecrm.dll/ecrm/scripts/prod_cat.jsp?oid=-8137)

direct links:

[http://www.infineon.com/cmc\\_upload/documents/040/841/ap1679\\_v1.1\\_2002\\_05\\_scanning\\_cpu22.pdf](http://www.infineon.com/cmc_upload/documents/040/841/ap1679_v1.1_2002_05_scanning_cpu22.pdf)

[http://www.infineon.com/cgi/ecrm.dll/ecrm/scripts/public\\_download.jsp?oid=40840&parent\\_oid=-8137](http://www.infineon.com/cgi/ecrm.dll/ecrm/scripts/public_download.jsp?oid=40840&parent_oid=-8137)

### - Individual Analysis of Assembler Source Code

With respect to problem CPU.22, all instructions of the C166 instruction set can be classified into the following groups:

- **Arithmetic/logic/data movement** instructions as successors of PUSH/PCALL (correctly) modify the condition flags in the PSW according to the result of the operation.
  - These instructions may **only** cause a problem if the **PSW** is a source or source/destination operand:
    - ADD/B, ADDC/B, CMP/B, CMPD1/2, CMPI1/2, SUB/B, SUBC/B
    - AND/B, OR/B, XOR/B
    - ASHR
    - MOV/B, MOVBZ/MOVBS
    - SCXT
    - PUSH, PCALL ; analysis must be repeated for successor of PUSH/PCALL
- The following instructions (most of them with immediate or register (Rx) addressing modes) can **never** cause a problem when they are successors of PUSH/PCALL:
  - CPL/B, NEG/B
  - DIV/U, DIVL/U, MUL/U
  - SHL/SHR, ROL/ROR, PRIOR
  - POP
  - RETI ; updates complete PSW with stacked value
  - RETP ; updates condition flags
  - PWRDN ; program restarts after reset
  - SRST ; program restarts

- **Conditional branch instructions** which may evaluate the Z flag as successors of PUSH/PCALL:
  - JB/JNB Z, *rel* ; directly evaluates Z flag
  - CALLA/CALLI, JMPA/JMPI/JMPR with the following condition codes
    - cc\_Z, cc\_EQ, cc\_NZ, cc\_NE
    - cc\_ULE, cc\_UGT, cc\_SLE, cc\_SGT
    - cc\_NET
- For these branch conditions, the branch may be performed in the wrong way.
- For other branch conditions, the branch target as well as the linear successor of the branch instruction must be analyzed (since these branch instruction don't modify the PSW flags).
- For **instructions that have no effect on the condition flags** and that don't evaluate the Z flag, the instruction that follows this instruction must be analyzed. These instructions are
  - NOP
  - ATOMIC, EXTxx
  - DISWDT, EINIT, IDLE, SRVWDT
  - CALLR, CALLS, JMPS ; branch target must be analyzed
  - RET, RETS ; return target must be analyzed (value pushed by PUSH/PCALL = return IP,
    - ; Z flag contains information whether intra-segment target address = 0000h or not)
  - TRAP ; both trap target and linear successor must be analyzed, since Z flag may be
    - ; incorrect in PSW on stack as well as in PSW at entry of trap routine
- For **bit modification instructions**, the problem may only occur if a source bit is the Z flag, and/or the destination bit is in the PSW, but not the Z flag. These instructions are:
  - BMOV/BMOVN
  - BAND/BOR/BXOR
  - BCMP
  - BFLDH
  - BFLDL ; problem only if bit 3 of @@ mask = 0, i.e. if Z is not selected
  - BCLR/BSET ; problem only if operand is not Z flag
  - JBC/JNBS ; wrong branch if operand is Z flag

## **CAN.9: Contents of Message Objects and Mask of Last Message Registers after Reset**

After any reset, the contents of the CAN Message Objects 1..15 (MCR, UAR, LAR, MCFG, Data[0:7]) and the Mask of Last Message Registers (LMLM, UMLM) may be undefined instead of unchanged (reset value 'X' instead of 'U').

This problem depends on temperature and the length of the reset, and differs from device to device. The problem is more likely (but not restricted) to occur at high temperature and for long hardware resets (> 100 ms).

### **Workaround:**

Re-initialize the CAN module after each reset.

## **CAN.7 Unexpected remote frame transmission**

### **Symptom**

The on-chip CAN module may send an unexpected remote frame with the identifier=0, when a pending transmit request of a message object is disabled by software.

### **Detailed Description**

There are three possibilities to disable a pending transmit request of a message object (n=1..14):

- Set CPUUPDn element
- Reset TXRQn element
- Reset MSGVALn element

Either of these actions will prevent further transmissions of message object n.

The symptom described above occurs when the CPU accesses CPUUPD, TXRQ or MSGVAL, while the pending transmit request of the corresponding message object is transferred to the CAN state machine (just before start of frame transmission). At this particular time the transmit request is transferred to the CAN state machine before the CPU prevents transmission. In this case the transmit request is still accepted from the CAN state machine. However the transfer of the identifier, the data length code and the data of the corresponding message object is prevented. Then the pre-charge values of the internal "hidden buffer" are transmitted instead, this causes a remote frame transmission with identifier=0 (11 bit) and data length code=0.

This behavior occurs only when the transmit request of message object n is pending and the transmit requests of other message objects are **not** active (single transmit request).

If this remote frame loses arbitration (to a data frame with identifier=0) or if it is disturbed by an error frame, it is **not** retransmitted.

### **Effects to other CAN nodes in the network**

The effect leads to delays of other pending messages in the CAN network due to the high priority of the Remote Frame. Furthermore the unexpected remote frame can trigger other data frames depending on the CAN node's configuration.

### **Workarounds**

1. The behavior can be avoided if a message object is not updated by software when a transmission of the corresponding message object is pending (TXRQ element is set) **and** the CAN module is active (INIT = 0). If a re-transmission of a message (e.g. after lost arbitration or after the occurrence of an error frame) needs to be cancelled, the TXRQ element should be cleared by software as soon as NEWDAT is reset from the CAN module.
2. The nodes in the CAN system ignore the remote frame with the identifier=0 and **no** data frame is triggered by this remote frame.

## Deviations from Electrical- and Timing Specification:

The following table lists the deviations of the DC/AC characteristics from the specification in the C167CS Data Sheet V2.2 2001-08:

Problem short name	Parameter	Symbol	Limit Values		Unit	Test Condition
			min.	max.		
DC.HYS.250	Input Hysteresis (Special Threshold)	HYS	250 instead of 400	-	mV	

### PLL.3.3: Increased PLL Jitter caused by external Access

#### Problem description:

In systems where the PLL is used for generation of the CPU clock frequency, the PLL jitter can increase under certain circumstances and exceed the specified value.

The value of the additional jitter is not a fixed one but it depends on the kind of activity on the external bus or output pins. The additional jitter increases with the number of output/bus pins which are switched at the same time to a new voltage level because the problem is caused by noise on the on-chip power supply.

The capacitive load of the used pins has also an influence to the additional jitter. A high capacitive load can increase the additional jitter.

#### Effects to the system:

All PLL factors are affected (PLL factor 1.5 / 2 / 2.5 / 3 / 4 / 5). The PLL jitter increases when access to the external bus or output pins is performed. This phenomenon has no influence to direct drive-, prescaler-, and SDD mode.

The problem does not affect the functionality of the CPU and the on-chip peripherals.

The additional jitter has the maximum effect if only one TCL is considered (period jitter). This can have an influence to the bus timings with one TCL.

The additional jitter decreases with the number of consecutive TCLs (accumulated jitter). The accumulated jitter has an effect on timings with more than one TCL (certain bus timings, CAN bus timing, serial interface).

#### New value of the PLL jitter


For an accumulated period of  $N \cdot \text{TCL}$  the new maximum jitter  $D_N[\text{ns}]$ , which exceeds the specified value in the Data Sheet, is computed using the formula:

$$D_N[\text{ns}] = \pm((460 / f_{\text{CPU}} + 4366 / f_{\text{CPU}}^2) * (N / T_m) + 0.25)$$

Were  $N$  = number of consecutive TCL,  $f_{\text{CPU}}$  = CPU frequency in MHz and  $T_m = f_{\text{CPU}} * 1.3$  .

This approximated formula is valid for a CPU frequency  $10 \text{ MHz} \leq f_{\text{CPU}} \leq 40 \text{ MHz}$  with the conditions:

$$\begin{aligned} T_m &= f_{\text{CPU}} * 1.3 && \text{for } N \leq T_m \\ T_m &= N && \text{for } N > T_m \end{aligned}$$



### Workaround:

In the case that the additional jitter causes problems in the system which cannot be relaxed with software adapted timing parameters the following workarounds are possible:

- If the clock generation is done with the on-chip oscillator then direct drive- or prescaler mode can be used.
- If the maximum frequency of the on-chip oscillator is not sufficient then an external clock generator can be used.

### A/D Converter Characteristics:

#### ADCC.2.5: ADC Overload Current

During exceptional conditions in the application system an overload current  $I_{OV}$  can occur on the analog inputs of the A/D converter when  $V_{AIN} > V_{DD}$  or  $V_{AIN} < V_{SS}$ . For this case, the following conditions are specified in the Data Sheet:

$$I_{OVmax} = | \pm 5 \text{ mA} |$$

The specified total unadjusted error  $TUE_{max} = | \pm 2 \text{ LSB} |$  @ Port 5 and  $TUE_{max} = | \pm 10 \text{ LSB} |$  @ PORT1 is guaranteed only if the absolute sum of input overload currents on all analog input pins does not exceed 10 mA.

Due to an internal problem, the specified TUE value is only met for a **positive** overload current  $0 \text{ mA} \leq I_{OV} \leq +5 \text{ mA}$  (all currents flowing into the microcontroller are defined as positive and all currents flowing out of it are defined as negative).

If the exceptional conditions in the application system cause a **negative** overload current, then the maximum TUE can be exceeded (depending on value of  $I_{OV}$ ,  $R_{AIN}$ ,  $R_{AREF}$  and  $R_{AGND}$ ):

## Port 5 Problem Description in Detail:

### 1. Overload Current at Analog channel AN0 - AN15

If a **negative** overload current  $I_{OV}$  occurs on analog input channel ANn, then an additional current  $I_{AN}$  (crosstalk current) is caused at the neighbour channels ANn-1 and ANn+1. This behavior causes an additional unadjusted error AUE to the ADC result.

Relation between  $I_{AN}$  and  $I_{OV}$ :

$$\begin{aligned} I_{ANn+1} &= \text{ovf-1} * I_{OVn} \\ I_{ANn-1} &= \text{ovf-1} * I_{OVn} \end{aligned}$$

### 2. Overload Current at Digital channel P7.7

A negative overload current  $I_{OV}$  at digital Port P7.7 causes an additional current  $I_{AN}$  at the analog input AN0. The relation between both channels is also defined by ovf-1:

$$I_{AN0} = \text{ovf-1} * I_{OVP7.7}$$

### 3. Overload Current at Analog channel AN12 – AN15 and influence to $V_{AREF}$

If an overload current  $I_{OV}$  occurs on analog input channel AN12 – AN15 then an additional current  $I_{AREF}$  (crosstalk current) is caused at pin  $V_{AREF}$ .

Depending on  $R_{AREF}$ , the internal resistance of the reference voltage, the crosstalk current  $I_{AREF}$  at pin  $V_{AREF}$  can cause an additional unadjusted error AUE to all other analog channels.

In case  $R_{AREF} \leq 2450 \text{ Ohm}$  [  $R_{AREF} \leq ((\text{LSB}/2) / (I_{OVmax} * \text{ovf-3})$  ] the maximum possible additional error to all other channels is smaller than 0.5 LSB with the condition of  $I_{OVmax} = |\pm 5 \text{ mA}|$  at AN12 - AN15.

Relation between  $I_{AREF}$  and  $I_{OV}$ :

$$I_{AREF} = \text{ovf-3} * I_{OVn} \quad (12 \leq n \leq 15)$$

**Note:** The influence to the reference voltage  $V_{AREF}$  caused by  $I_{OVn}$  (shift of  $V_{AREF}$ ) is maximum for  $V_{AINn} = V_{AREF}$  and the influence is minimum for  $V_{AINn} = 0V$ . The condition  $R_{AREF} \leq 2450 \text{ Ohm}$  and 0.5 LSB is calculated for the worst case at  $V_{AINn} = V_{AREF}$ .

### 4. Values of ovf-1 and ovf-3

Parameter	Symbol	Min	Max
Overload factor-1	ovf-1	- 0.0001	0
Overload factor-3	ovf-3	- 0.0002	0

These Values are the absolute **maximum values measured in the lab and not tested!**

### 5. Effects on the Conversion Result and TUE

The effect on the conversion result and the TUE has to be calculated based on the crosstalk current and the impedance of the analog source  $R_{ASRC}$ .  $I_{ANn}$  causes an external voltage  $U_{\Delta n}$  at the analog channel ANn (same principle for  $V_{AREF}$  and  $V_{AGND}$ ) which is the reason for an additional unadjusted error **AUE** of the conversion result. This AUE can increase the specified total unadjusted error TUE (Specified value: TUE =  $\pm 2$  LSB). The voltage  $U_{\Delta n}$  is nearly independent on the voltage value of the analog source.

$$\begin{aligned} U_{\Delta n} &= I_{ANn} * R_{ASRC} \\ U_{\Delta AREF} &= I_{AREF} * R_{AREF} \\ U_{\Delta AGND} &= I_{AGND} * R_{AGND} \\ \text{AUE} &= U_{\Delta n} / 1 \text{ LSB} \\ \text{TUE} &= (\pm 2 \text{ LSB}) \pm \text{AUE} \end{aligned} \quad [U_{\Delta n} \text{ in mV and LSB in mV}]$$

**Note:** A negative overload current  $I_{OVn}$  decreases the analog signal voltage  $V_{AINn}$  and causes a negative AUE.

## 6. Calculation Example

Assumed system values:

$$\begin{aligned} I_{OV4} &= -1 \text{ mA} && \text{negative overload current at P5.4} \\ R_{ASRC} &= 20 \text{ kOhm} && \text{resistance of the external sensor at P5.5} \\ V_{AREF} &= 5 \text{ V} && 1 \text{ LSB} = 4.9 \text{ mV} \\ R_{AREF} &\text{ has to be considered for } I_{OV} \text{ at ANn (12} \leq n \leq 15) \\ R_{AREF} &= 500 \text{ Ohm} && \rightarrow V_{AREF} \text{ shift error is negligible} \end{aligned}$$

$$\begin{aligned} I_{AN5} &= \text{ovf1} * I_{OV4} \\ I_{AN5} &= (-1.0 * E-4) * (-1 \text{ mA}) \\ I_{AN5} &= 0.10 \text{ } \mu\text{A} \end{aligned}$$

$$\begin{aligned} U_{\Delta 5} &= I_{AN5} * R_{ASRC} \\ U_{\Delta 5} &= 0.10 \text{ } \mu\text{A} * 20 \text{ kOhm} \\ U_{\Delta 5} &= 2.0 \text{ mV} \end{aligned}$$

$$\begin{aligned} \text{AUE} &= U_{\Delta n} / 1 \text{ LSB} \\ \text{AUE} &= 2.0 \text{ mV} / 4.9 \text{ mV} \\ \text{AUE} &= 0.41 \text{ LSB} \end{aligned}$$

**Result:** The negative overload current  $I_{OV4}$  of this system example can distort the real result of AN5 by an additional unadjusted error,  $0 \text{ LSB} \leq \text{AUE} \leq 0.41 \text{ LSB}$ .

The TUE is in the range of  $-2.41 \text{ LSB} \leq \text{TUE} \leq 2.0 \text{ LSB}$ .

## PORT1 Problem Description in Detail:

### 1. Overload Current at analog channel AN16 – AN23

If a **negative** overload current  $I_{OV}$  occurs on analog input channel ANn, then an additional current  $I_{AN}$  (crosstalk current) is caused at the neighbour channels ANn-1 and ANn+1. This behavior causes an additional unadjusted error AUE to the ADC result.

Relation between  $I_{AN}$  and  $I_{OV}$ :

$$\begin{aligned} I_{ANn+1} &= \text{ovf-11} * I_{OVn} \\ I_{ANn-1} &= \text{ovf-11} * I_{OVn} \end{aligned}$$

### 2. Overload Current at digital channel P0H.7

A negative overload current  $I_{OV}$  at digital Port P0H.7 causes an additional current  $I_{AN}$  at the analog input AN16. The relation between both channels is also defined by ovf-11:

$$I_{AN0} = \text{ovf-11} * I_{OV P0H.7}$$

### 3. Values of ovf-11

Parameter	Symbol	Min	Max
Overload factor-11	ovf-11	- 0.0008	0

This value is the absolute **maximum value measured in the lab and is not tested!**

## History List (since C167CS-4RM/LM device step (E)ES-AA)

### Functional Problems

Functional Problem	Short Description	Fixed in step
PWRDN.1	Execution of PWRDN Instruction while pin NMI# = high	
SYSCON1.1	Reset Value in Register SYSCON1	ES-BA
(POWER.19	SW- or WDT-Reset while SDD mode is active	see RST.9)
POWER.16	SDD and Sleep Mode cannot be terminated	ES-AC
POWER.15	Wake Up from Sleep Mode not possible in Prescaler Mode	
POWER.10	Sleep Mode: CAN and ADC Modules enabled	ES-AB
POWER.8	Termination of Sleep Mode with HW Reset	(E)ES-AA
BUS.18	PEC transfers after JMPR	(E)ES-AA
BUS.19	Unlatched Chip Selects at Entry into Hold Mode	ES-BA
CPU.21	BFLDL/BFLDH Instructions after Write Operations to internal IRAM	
CPU.22	Z Flag after PUSH and PCALL	
RST.15.2	New Behaviour: Software/Watchdog/Short HW reset during Slow Down operation with PLL off (not for Ax-steps)	
RST.13	Power-up with Missing Clock	ES-AB
RST.11	Missing clock at XTAL1	ES-AB
RST.9	Software/Watchdog/Short HW reset during Slow Down operation with PLL off (Ax-steps only, see also RST.15.2)	ES-BA
RST.8	Clock failure detection during external reset	ES-BA
RST.7	Latching of P0 Reset Configuration when pin EA# = high	(E)ES-AA
RST.5	HW Reset not detected in PLL Mode during Slow Down operation when PLL is switched off	(E)ES-AA
CAPCOM.4	SW Access to P1H Overwrites CAPCOM HW Settings	
ADC.11	Modifications of ADM field while bit ADST = 0	
TCOMP.2	Pad Driver Temperature Compensation does not work properly (AA-steps)	ES-AB
TCOMP.3	Pad Driver Temperature Compensation disabled (AB/AC-steps) - see also note about documentation update	ES-BA
CAN.7	Unexpected Remote Frame Transmission	
CAN.9	Contents of Message Objects and Mask of Last Message Registers after Reset	
X9	Read Access to XPERs in Visible Mode	
X17	XBUS Access after External Access with EWEN = 1 and/or BSWC = 1	

## AC/DC Deviations

AC/DC Deviation	Short Description	Fixed in step
AC.t34.4	t34 (min): CLKOUT rising to ALE falling edge relaxed to -2ns - included in specification for tc11: -3 .. +6 ns	see Data Sheet
DC.VILS.2	Input low voltage (special threshold) $V_{ILS}$ (max) relaxed to 1.8 V	ES-BA
DC.HYS.2	Hysteresis (special threshold) relaxed to 200 mV (Ax-steps only)	ES-BA
DC.HYS.250	Hysteresis (special threshold) relaxed to 250 mV (BA-steps)	
AC.PLL.1	PLL Jitter > 3.8 % for fcpu < 12 MHz	ES-AC
PLL.3.1	Increased PLL Jitter caused by External Access (step AB only)	ES-AC
PLL.3.2	Increased PLL Jitter caused by External Access (step AC only)	ES-BA
PLL.3.3	Increased PLL Jitter caused by External Access (step BA)	
DC.IIDX.1	Idle Mode Supply Current 65 mA @ 25 MHz	see DC.IID_PD.1
DC.IID_PD.1	Idle and Power Down Mode Supply Currents: not tested	see Data Sheet V2.2
ADCC.2.4	ADC Overload Current (AA-steps only)	ES-AB
ADCC.2.5	ADC Overload Current (not for AA-steps)	

# Documentation Update - Modifications of Features

(reference: C167CS User's Manual V2.0, 2000-07)

- **Registers P5DIDIS, P1DIDIS now implemented**

In the **Ax** -steps of the C167CS-4RM/LM, registers P5DIDIS and P1DIDIS are **not** implemented. They are implemented beginning with step **BA**.

- **Single Chip Mode Reset eliminated** (p. 20-20 to p. 20-24)

**Note:** the **Single Chip Mode Reset** feature has been eliminated beginning with the BA-step of the C167CS-LM/4RM: it will always read the reset configuration from PORT0, independent of the state (low or high) of pin EA#. However, the possibility to modify the configuration via register RSTCON will still be provided. See also Application Note AP1637 'Reset and System Startup Configuration via PORT0 or Register RSTCON'

[http://www.infineon.com/cmc\\_upload/migrated\\_files/document\\_files/Application\\_Notes/ap163703.pdf](http://www.infineon.com/cmc_upload/migrated_files/document_files/Application_Notes/ap163703.pdf)

This change ensures hardware compatibility with existing systems which are based on the C167CS-32FM up to step CB, C167CS-LM, C167CR-xx (all steps), and C167CS-4RM step BA or higher.

- **Pad Driver Temperature Compensation**

The description of the pad driver temperature compensation mechanism has been removed from User's Manual V2.0.

For systems which were using this feature before, the functionality which is implemented in the **BA**-step is described in the following:

To avoid a malfunction and additional current consumption, the on chip pad driver temperature compensation is disabled by default after reset. For this reason, the functionality of some bits has been changed:

- PTCR.3/TCE = 0 (default after reset) means that the temperature compensation sensor is disabled
- TCV = 11 (default after reset) means that the pad drivers operate with maximum driver strength

No special action is necessary if normal (strong) pad drivers shall be used. Otherwise bit field TCC may be modified and bit TCS should be set to '1' to control the pad drivers via software.

# Application Hints

## Handling of the SSC Busy Flag (SSCBSY)

In master mode of the High-Speed Synchronous Serial Interface (SSC), when register SSCTB has been written, flag SSCBSY is set to '1' when the baud rate generator generates the next internal clock pulse. The maximum delay between the time SSCTB has been written and flag SSCBSY=1 is up to 1/2 bit time. SSCBSY is cleared 1/2 bit time after the last latching edge.

When polling flag SSCBSY after SSCTB has been written, SSCBSY may not yet be set to '1' when it is tested for the first time (in particular at lower baud rates). Therefore, e.g. the following alternative methods are recommended:

1. test flag SSCRIR (receive interrupt request) instead of SSCBSY (in case the receive interrupt request is not serviced by CPU interrupt or PEC), e.g.

```
loop:    BCLR SSCRIR                ;clear receive interrupt request flag
         MOV SSCTB, #xyz           ;send character
wait_tx_complete:
         JNB SSCRIR, wait_tx_complete ;test SSCRIR
         JB SSCBSY, wait_tx_complete ;test SSCBSY to achieve original
                                     timing(SSCRIR may be set 1/2 bit
                                     time before SSCBSY is cleared)
```

2. use a software semaphore bit which is set when SSCTB is written and is cleared in the SSC receive interrupt routine

## Note on Interrupt Register behaviour of the CAN module

Due to the internal state machine of the CAN module, a specific delay has to be considered between resetting INTPND and reading the updated value of INTID. See Application Note AP2924 "Interrupt Register behaviour of the CAN module in Siemens 16-bit Microcontrollers"

[http://www.infineon.com/cmc\\_upload/migrated\\_files/document\\_files/Application\\_Notes/ap292401.pdf](http://www.infineon.com/cmc_upload/migrated_files/document_files/Application_Notes/ap292401.pdf)

## Oscillator Watchdog and Prescaler Mode

The OWD replaces the missing oscillator clock signal with the PLL clock (base frequency).

- In **direct drive** mode the PLL base frequency is used directly (fcpu = 2...5 MHz).
- In **prescaler** mode the PLL base frequency is divided by 2 (fcpu = 1...2.5 MHz).

(see also C167CS User's Manual V2.0, p.6-8)

## Maintenance of ISNC register

The RTC and PLL interrupts share one interrupt node (XP3IC). If an interrupt request occurs the request bit in the Interrupt Subnode Control register has to be checked and cleared by software. To avoid a conflict with the next hardware interrupt request it is recommended to first clear both the request and the enable bit, and then to set the enable bit again.

Example for a RTC interrupt service routine (for Tasking C compiler):

```
...
If (RTCIR)
{
    _bfld (ISNC, 0x0003, 0x0000); // clear RTCIE and RTCIR
    _putbit (1, ISNC, 1);        // set RTCIE
}
...
```

In assembly language:

```
...
EXTR    #1
JNB     RTCIR, no_rtc_request
EXTR    #2          ; no further interruption of this sequence possible
BFLDL   ISNC, #03h, #00h ; clear RTCIE and RTCIR
BSET    RTCIE          ; set RTCIE
...
no_rtc_request:
```

## Type\_RE Oscillator Configuration for Low Power Operation

The type\_RE main oscillator is optimized for oscillation with a crystal within a frequency range of 4...40 MHz. In order to achieve minimum power consumption in power saving modes where the oscillator remains active, the size of the external components (Cx1, Cx2, Rx2) of a crystal oscillator circuit may be reduced below the values which are listed in AP2420xx 'Crystal Oscillator of the C500 and C166 Microcontroller Families'

[http://www.infineon.com/cgi/ecrm.dll/ecrm/scripts/prod\\_cat.jsp?oid=-8137](http://www.infineon.com/cgi/ecrm.dll/ecrm/scripts/prod_cat.jsp?oid=-8137)

direct link: [http://www.infineon.com/cmc\\_upload/documents/009/746/ap242005.pdf](http://www.infineon.com/cmc_upload/documents/009/746/ap242005.pdf)

The recommended minimum values for the external circuits are equal to the values which are listed in AP2420xx for the Type\_LP2 oscillator.

It is strongly recommended to measure the resulting safety factor (negative resistance method) in the final target system (layout) to ensure sufficient start-up reliability. Please refer to the limits specified by the crystal supplier.

## PLL lock after temporary clock failure

When the PLL is locked and the input clock at XTAL1 is interrupted then the PLL becomes unlocked, provides the base frequency (2 ... 5 MHz) and the PLL unlock interrupt request flag is set. If the XTAL1 input clock starts oscillation again then the PLL stays in the PLL base frequency. The CPU clock source is only switched back to the XTAL1 oscillator clock after a hardware reset. This can be achieved via a normal hardware reset or via a software reset with enabled bidirectional reset. It is important that the hardware reset is at least active for 1 ms, after that time the PLL is locked in any case.

## Note on Early (Unlatched) Chip Select Option

As described in the User's Manuals (e.g. C167CS User's Manual, V2.0, 2000-07, p.9-11), an early (unlatched) address chip select signal (SYSCON.CSCFG = '1') becomes active together with the address and BHE (if enabled) and remains active until the end of the current bus cycle. Early address chip select signals are not latched internally and may toggle intermediately while the address is changing.

These effects may also occur on CSx# lines which are configured as RDCSx# and/or WRCSx# signals (BUSCONx.CSRENx = 1 and/or CSWENx = 1).

The position of these transitions (spikes) is at the beginning of an external bus cycle or an internal XBUS cycle, indicated by the rising edge of signal ALE. The width of these transitions is ~ 5 ns (measured at a reference level of 2.0 V with Vdd = 5.0 V). The falling edge of the spike occurs in the same relation to RD#, WR#/WRH#/WRL# and to other CS# signals as if it was an address chip select signal with early chip select option.

When CS# lines configured as RDCS# and/or WRCS# are used e.g. as output enable (OE#) signals for external devices or as clock input for shift registers, problems might occur (temporary bus contention during data float times (may be solved by tristate wait state), unexpected shift operations, etc.). When CS# lines configured as WRCS# are used as write enable (WE#) signals for external devices or FIFOs, internal locations may be overwritten with undefined data.

When CS# lines are used as chip enable (CE#) signals for external memories, usually no problems are expected, since the falling edge of the spikes has the same characteristics as the falling edge of an access with a regular early (unlatched) address CS# signal. At this time, the memory control signals RD#, WR# (WRH#/WRL#) are on their inactive (high) levels.

Application Support Group, Munich

[http://www.infineon.com/cgi/ecrm.dll/ecrm/scripts/prod\\_cat.jsp?oid=-8137](http://www.infineon.com/cgi/ecrm.dll/ecrm/scripts/prod_cat.jsp?oid=-8137)