



Please note that Cypress is an Infineon Technologies Company.

The document following this cover page is marked as “Cypress” document as this is the company that originally developed the product. Please note that Infineon will continue to offer the product to new and existing customers as part of the Infineon product portfolio.

Continuity of document content

The fact that Infineon offers the following product as part of the Infineon product portfolio does not lead to any changes to this document. Future revisions will occur when appropriate, and any changes will be set out on the document history page.

Continuity of ordering part numbers

Infineon continues to support existing part numbers. Please continue to use the ordering part numbers listed in the datasheet for ordering.



THIS SPEC IS OBSOLETE

Spec No: 001-14655

Spec Title: IBIS4-14000 FREQUENTLY ASKED QUESTIONS
- AN6020

Sunset Owner: Evelyn Beard (EYB)

Replaced by: None

IBIS4-14000 Frequently Asked Questions - AN6020

Table of Contents

1. Why do some sensors have dark rows that move in correlation with the integration time?	1
2. Are the pixels more sensitive in sub-sample mode than in full resolution?	3
3. What is the cause of the banding in the image?	3
4. What is the cause of the gray shades visible in a white to black transition	4

1. Why do some sensors have dark rows that move in correlation with the integration time?

This phenomenon is visible when there is a defect row in the pixel array. The reset or readout of a defect row can disturb the reset or readout of the other row (both Y shift-registers select a different row simultaneously; the difference between these rows is the integration time). The reset or readout of a defect line draws more current in the columns as expected and this disturbs the readout or reset of the other line.



Figure 1. Defect Line Moves in Correlation with the Integration Time

Figure 1 shows an image taken with an integration time of 1000 lines. The defect line 3422 (in the middle) can be seen at location 2422 and 4422. Note that these images were amplified heavily to make the effect more visible.

The moving line problem can be solved by not reading out the defect line. This can be done by reading out the line before the defect line twice (suppressing of the CLK_YL pulse). When the line before the defect is readout twice, two succeeding CLK_YL pulses should be asserted. This way, the defect line is skipped and shall not influence the reset voltage of the row that is currently being reset.

Figure 2 shows the timing that should be used when a line is defect. The timing assumes that the third line is defect.




Figure 2. Modified Timing; in this case line 3 is defect and skipped

Figure 3 shows the full line readout sequence with the modified timing. The row before the defect is readout twice (CLK_YL is suppressed). Two CLK_YL pulses after the same line has been readout will skip the defect line.





Figure 3. Modified Line Readout Sequence

2. Are the pixels more sensitive in sub-sample mode than in full resolution?

When Y-sub sampling is enabled, certain rows will not be readout and reset. These lines will saturate. As a consequence, some of the generated electrons will not be picked up by the saturated pixel but by the neighboring pixels. This problem can be solved by asserting extra CLK_Y and RESET pulses, to quickly reset the unwanted lines, instead of using the Y sub sample modes.

3. What is the cause of the banding in the image?

The banding is caused when vertical blanking is used to increase the integration time (delaying the assertion of SYNC_Y). When one of the Y-shift register points to the end of the image array, a SYNC_Y pulse will reset this shift register. If SYNC_Y is not asserted, the Y-shift register will be clocked out of the array while the other Y-shift register is still within the pixel array. This causes a voltage offset in the pixel. Both Y-shift registers should always be pointing in the array to eliminate this effect. When integration times longer than the frame readout time are required, one should apply horizontal blanking, i.e., program additional delay times at the end of each row. It is very important that the SYNC_Y and Y_CLOCK pulses are always asserted with the same interval.



4. What is the cause of the gray shades visible in a white to black transition

Note: this effect is only visible when the image is amplified.

The resistance of the NMOS switches increases for larger signals (smaller V_{gs}). When $V_{DD} = 3.3V$ this resistance is too high, which causes a gray shade in the black pixel when this is proceeded by a white pixel.

There are 2 solutions:

5. Increase V_{DD} to 4V—this will lower the resistance of the NMOS switches (increases V_{gs}). This is, however, not recommended, since this will decrease the lifetime of the image sensor.
6. Decrease V_{DDR} to 3.3V—this will lower the signal swing, causing a decrease of the resistance of the NMOS switches (increases V_{gs}). This decrease in signal swing can be neglected because the image is amplified (or else the effect would not have been visible) and thus the full signal swing is never used.

All product and company names mentioned in this document are the trademarks of their respective holders.

Cypress Semiconductor
198 Champion Court
San Jose, CA 95134-1709
Phone: 408-943-2600
Fax: 408-943-4730
<http://www.cypress.com>

© Cypress Semiconductor Corporation, 2006-2013. The information contained herein is subject to change without notice. Cypress Semiconductor Corporation assumes no responsibility for the use of any circuitry other than circuitry embodied in a Cypress product. Nor does it convey or imply any license under patent or other rights. Cypress products are not warranted nor intended to be used for medical, life support, life saving, critical control or safety applications, unless pursuant to an express written agreement with Cypress. Furthermore, Cypress does not authorize its products for use as critical components in life-support systems where a malfunction or failure may reasonably be expected to result in significant injury to the user. The inclusion of Cypress products in life-support systems application implies that the manufacturer assumes all risk of such use and in doing so indemnifies Cypress against all charges.

This Source Code (software and/or firmware) is owned by Cypress Semiconductor Corporation (Cypress) and is protected by and subject to worldwide patent protection (United States and foreign), United States copyright laws and international treaty provisions. Cypress hereby grants to licensee a personal, non-exclusive, non-transferable license to copy, use, modify, create derivative works of, and compile the Cypress Source Code and derivative works for the sole purpose of creating custom software and or firmware in support of licensee product to be used only in conjunction with a Cypress integrated circuit as specified in the applicable agreement. Any reproduction, modification, translation, compilation, or representation of this Source Code except as specified above is prohibited without the express written permission of Cypress.

Disclaimer: CYPRESS MAKES NO WARRANTY OF ANY KIND, EXPRESS OR IMPLIED, WITH REGARD TO THIS MATERIAL, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE. Cypress reserves the right to make changes without further notice to the materials described herein. Cypress does not assume any liability arising out of the application or use of any product or circuit described herein. Cypress does not authorize its products for use as critical components in life-support systems where a malfunction or failure may reasonably be expected to result in significant injury to the user. The inclusion of Cypress' product in a life-support systems application implies that the manufacturer assumes all risk of such use and in doing so indemnifies Cypress against all charges.

Use may be limited by and subject to the applicable Cypress software license agreement.