

Please note that Cypress is an Infineon Technologies Company.

The document following this cover page is marked as “Cypress” document as this is the company that originally developed the product. Please note that Infineon will continue to offer the product to new and existing customers as part of the Infineon product portfolio.

Continuity of document content

The fact that Infineon offers the following product as part of the Infineon product portfolio does not lead to any changes to this document. Future revisions will occur when appropriate, and any changes will be set out on the document history page.

Continuity of ordering part numbers

Infineon continues to support existing part numbers. Please continue to use the ordering part numbers listed in the datasheet for ordering.



The following document contains information on Cypress products. The document has the series name, product name, and ordering part numbering with the prefix “MB”. However, Cypress will offer these products to new and existing customers with the series name, product name, and ordering part number with the prefix “CY”.

How to Check the Ordering Part Number

1. Go to www.cypress.com/pcn.
2. Enter the keyword (for example, ordering part number) in the **SEARCH PCNS** field and click **Apply**.
3. Click the corresponding title from the search results.
4. Download the Affected Parts List file, which has details of all changes

For More Information

Please contact your local sales office for additional information about Cypress products and solutions.

About Cypress

Cypress is the leader in advanced embedded system solutions for the world's most innovative automotive, industrial, smart home appliances, consumer electronics and medical products. Cypress' microcontrollers, analog ICs, wireless and USB-based connectivity solutions and reliable, high-performance memories help engineers design differentiated products and get them to market first. Cypress is committed to providing customers with the best support and development resources on the planet enabling them to disrupt markets by creating new product categories in record time. To learn more, go to www.cypress.com.

June 06, 2012

Chip Errata for the MB9AB40N/A40N/340N/140N Series, FM3 Family Microcontroller

This document describes the errata for the MB9AB40N/A40N/340N/140N Series FM3 Family Microcontroller. Details include Flash memory dual operation problems, scope of impact and available workarounds. Compare this document to the device's data sheet for a complete functional description.

Contact your local Cypress Sales Representative if you have questions.

Part Numbers Affected

Part Number
MB9AB40N/A40N/340N/140N Series

Problem Description

In the FLASH macro mounted on the target products in Item 3, two problems were found.

We would provide the information on the problems and their countermeasures.

Please accept our apology for the inconvenience caused by these failures.

We appreciate if you confirm the failures described in this document and take the appropriate countermeasures.

Outline of Problem1

During writing (programming) to FLASH memory of an upper bank, FLASH memory of a lower bank could not be read at a specific timing in some operation combination.

Outline of Problem 2


When writing is executed during sector erase suspend, FLASH memory could not be read correctly at a specific timing.

Problem Conditions

(1) Occurrence Conditions of Problem 1

At the specific timing, the FLASH memory lower bank (smaller sector) is not correctly read while writing(programming) to the FLASH memory upper bank (larger sector). Therefore, the instruction in the lower bank could not be read correctly and the writing sequence to the upper bank executed by the instruction would lead to a hard fault or run-away. Moreover, when the lower bank is read while writing to the upper bank by the instruction on RAM, an incorrect value might be read.

Figure 1. FLASH Memory MAP



The problem occurs at the combination of the following operations.

Upper bank (Larger sector)	Lower bank (Smaller sector)	Judgment
Instruction/data reading		Normal operation
Instruction/data reading	Writing	Normal operation
Instruction/data reading	Sector erase	Normal operation
Writing	Instruction/data reading	At a specific timing, a correct value could not be read.
Sector erase	Instruction/data reading	Normal operation
FLASH memory(all sectors) erase		Normal operation

(2) Occurrence Condition of Problem 2

When writing to the upper bank or the lower bank at a sector erase suspend, reading to the opposite bank might result in reading of an incorrect value at a specific timing. Therefore, FLASH memory could not be correctly read in the following flow, and a hard fault or a run-away might occur.

- (a) Erase a sector of the lower bank.
- (b) Suspend the sector erase operation.
- (c) Write to a different sector of the lower bank.
- (d) Execute an instruction in the upper bank.

Different from Problem 1, this problem would occur in the reverse operation combination of used banks.

The problem occurs at some combinations of the following operations.

Operation during suspend		Judgement
Upper bank (Larger sector)	Lower bank (Smaller sector)	
Instruction/data reading		Normal operation
Instruction/data reading	Writing	At a specific timing, a correct value cannot be read.
Writing	Instruction/data reading	

Affected Devices

The following devices are affected:

Series names	Part number of affected products
MB9A140N series	MB9AF141L, MB9AF141M, MB9AF141N MB9AF142L, MB9AF142M, MB9AF142N MB9AF144L, MB9AF144M, MB9AF144N
MB9A340N series	MB9AF341L, MB9AF341M, MB9AF341N MB9AF342L, MB9AF342M, MB9AF342N MB9AF344L, MB9AF344M, MB9AF344N
MB9AA40N series	MB9AFA41L, MB9AFA41M, MB9AFA41N MB9AFA42L, MB9AFA42M, MB9AFA42N MB9AFA44L, MB9AFA44M, MB9AFA44N
MB9AB40N series	MB9AFB41L, MB9AFB41M, MB9AFB41N MB9AFB42L, MB9AFB42M, MB9AFB42N MB9AFB44L, MB9AFB44M, MB9AFB44N

Affected Modules

This problem is affecting the operation of the FLASH memory

Root Cause

The failures are caused by design mistake.

Workaround

To solve these problems we would re-design the circuit of the affected devices.

Before the re-design, the problems could be avoided by taking the following countermeasures:

- Countermeasures against Problem 1

To rewrite the upper bank of FLASH memory, store the write instruction in RAM instead of the lower bank and read the instruction from RAM to execute. Do not access the lower bank until the write operation is completed (RDY=1). Especially to disable the vector fetch to the lower bank of the FLASH memory at an interrupt occurred, the interrupt should be prohibited or the vector address should be set to RAM by the vector table offset register.

- Countermeasures against Problem 2

We could not provide an effective countermeasure against Problem 2.

So, do not execute the write operation to a different sector in the same bank at sector erase suspend.

Corrective action by Cypress Semiconductor

Cypress Semiconductor will correct these problems by a redesign of the affected devices

New part numbers are made by adding "A" at the end of the previous product types and new device delivery schedule is as follows:

Series name or product type	ES Delivery Date	Mass-production Start Date
MB9AF141LA, MB9AF141MA, MB9AF141NA MB9AF142LA, MB9AF142MA, MB9AF142NA MB9AF144LA, MB9AF144MA, MB9AF144NA	The 31st of August, 2012	The 28th of September, 2012
MB9AF341LA, MB9AF341MA, MB9AF341NA MB9AF342LA, MB9AF342MA, MB9AF342NA MB9AF344LA, MB9AF344MA, MB9AF344NA	The 31st of August, 2012	The 28th of September, 2012
MB9AFA41LA, MB9AFA41MA, MB9AFA41NA MB9AFA42LA, MB9AFA42MA, MB9AFA42NA MB9AFA44LA, MB9AFA44MA, MB9AFA44NA	The 31st of August, 2012	The 28th of September, 2012
MB9AFB41LA, MB9AFB41MA, MB9AFB41NA MB9AFB42LA, MB9AFB42MA, MB9AFB42NA MB9AFB44LA, MB9AFB44MA, MB9AFB44NA	The 31st of August, 2012	The 28th of September, 2012

Document History Page

Document Title: Chip Errata for the MB9AB40N/A40N/340N/140N Series, FM3 Family Microcontroller Document Number: 002-04518			
Rev.	ECN No.	Orig. of Change	Description of Change
**	—	YUIS	Initial release
*A	5232550	YUIS	Migrated to Cypress format

Cypress Semiconductor
198 Champion Court
San Jose, CA 95134-1709
Phone: 408-943-2600
Fax: 408-943-4730
<http://www.cypress.com>

© Cypress Semiconductor Corporation, 2012-2016. This document is the property of Cypress Semiconductor Corporation and its subsidiaries, including Spansion LLC ("Cypress"). This document, including any software or firmware included or referenced in this document ("Software"), is owned by Cypress under the intellectual property laws and treaties of the United States and other countries worldwide. Cypress reserves all rights under such laws and treaties and does not, except as specifically stated in this paragraph, grant any license under its patents, copyrights, trademarks, or other intellectual property rights. If the Software is not accompanied by a license agreement and you do not otherwise have a written agreement with Cypress governing the use of the Software, then Cypress hereby grants you a personal, non-exclusive, nontransferable license (without the right to sublicense) (1) under its copyright rights in the Software (a) for Software provided in source code form, to modify and reproduce the Software solely for use with Cypress hardware products, only internally within your organization, and (b) to distribute the Software in binary code form externally to end users (either directly or indirectly through resellers and distributors), solely for use on Cypress hardware product units, and (2) under those claims of Cypress's patents that are infringed by the Software (as provided by Cypress, unmodified) to make, use, distribute, and import the Software solely for use with Cypress hardware products. Any other use, reproduction, modification, translation, or compilation of the Software is prohibited.

TO THE EXTENT PERMITTED BY APPLICABLE LAW, CYPRESS MAKES NO WARRANTY OF ANY KIND, EXPRESS OR IMPLIED, WITH REGARD TO THIS DOCUMENT OR ANY SOFTWARE OR ACCOMPANYING HARDWARE, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE. To the extent permitted by applicable law, Cypress reserves the right to make changes to this document without further notice. Cypress does not assume any liability arising out of the application or use of any product or circuit described in this document. Any information provided in this document, including any sample design information or programming code, is provided only for reference purposes. It is the responsibility of the user of this document to properly design, program, and test the functionality and safety of any application made of this information and any resulting product. Cypress products are not designed, intended, or authorized for use as critical components in systems designed or intended for the operation of weapons, weapons systems, nuclear installations, life-support devices or systems, other medical devices or systems (including resuscitation equipment and surgical implants), pollution control or hazardous substances management, or other uses where the failure of the device or system could cause personal injury, death, or property damage ("Unintended Uses"). A critical component is any component of a device or system whose failure to perform can be reasonably expected to cause the failure of the device or system, or to affect its safety or effectiveness. Cypress is not liable, in whole or in part, and you shall and hereby do release Cypress from any claim, damage, or other liability arising from or related to all Unintended Uses of Cypress products. You shall indemnify and hold Cypress harmless from and against all claims, costs, damages, and other liabilities, including claims for personal injury or death, arising from or related to any Unintended Uses of Cypress products.

Cypress, the Cypress logo, Spansion, the Spansion logo, and combinations thereof, PSoC, CapSense, EZ-USB, F-RAM, and Traveo are trademarks or registered trademarks of Cypress in the United States and other countries. For a more complete list of Cypress trademarks, visit cypress.com. Other names and brands may be claimed as property of their respective owners.