



---

The following document contains information on Cypress products. Although the document is marked with the name "Spansion" and "Fujitsu", the company that originally developed the specification, Cypress will continue to offer these products to new and existing customers.

**Continuity of Specifications**

There is no change to this document as a result of offering the device as a Cypress product. Any changes that have been made are the result of normal document improvements and are noted in the document history page, where supported. Future revisions will occur when appropriate, and changes will be noted in a document history page.

**Continuity of Ordering Part Numbers**

Cypress continues to support existing part numbers. To order these products, please use only the Ordering Part Numbers listed in this document.

**For More Information**

Please contact your local sales office for additional information about Cypress products and solutions.

**About Cypress**

Cypress (NASDAQ: CY) delivers high-performance, high-quality solutions at the heart of today's most advanced embedded systems, from automotive, industrial and networking platforms to highly interactive consumer and mobile devices. With a broad, differentiated product portfolio that includes NOR flash memories, F-RAM™ and SRAM, Traveo™ microcontrollers, the industry's only PSoC® programmable system-on-chip solutions, analog and PMIC Power Management ICs, CapSense® capacitive touch-sensing controllers, and Wireless BLE Bluetooth® Low-Energy and USB connectivity solutions, Cypress is committed to providing its customers worldwide with consistent innovation, best-in-class support and exceptional system value.

## Errata

This errata sheet is for MB90480/485 Series Hardware Manual Rev.7 (CM44-10121-7E)

F<sup>2</sup>MC-16LX  
16-BIT MICROCONTROLLER  
MB90480/485 Series  
HARDWARE MANUAL

2009.1.9

Page	Item	Description																		
507	24.1	<p>"Table 24.1-1 Function of Pins" was corrected as indicated by the shading below.</p> <p>(Error)</p> <table border="1"> <thead> <tr> <th>Pin</th><th>Function</th><th>Additional information</th></tr> </thead> <tbody> <tr> <td>MD2,MD1,MD0</td><td>Mode pin</td><td>Setting MD2=1, MD1=1, and MD0=0 to enter the serial programming mode.</td></tr> <tr> <td>X0,X1</td><td>Oscillation pin</td><td>As, in the serial programming mode, CPU internal operation clock is the PLL clock multiplied-by-1, the internal operation clock frequency is equal to the oscillation clock frequency. Consequently, the frequencies that can be input to the high-speed oscillation input pin for serial writing are from 4.5 MHz to 25 MHz.</td></tr> </tbody> </table> <p>(Correct)</p> <table border="1"> <thead> <tr> <th>Pin</th><th>Function</th><th>Additional information</th></tr> </thead> <tbody> <tr> <td>MD2,MD1,MD0</td><td>Mode pin</td><td>Setting MD2=1, MD1=1, and MD0=0 to enter the serial programming mode.</td></tr> <tr> <td>X0,X1</td><td>Oscillation pin</td><td>As, in the serial programming mode, CPU internal operation clock is the PLL clock multiplied-by-1, the internal operation clock frequency is equal to the oscillation clock frequency. Consequently, the frequencies that can be input to the high-speed oscillation input pin for serial writing are from 4 MHz to 25 MHz.</td></tr> </tbody> </table> <p style="text-align: right;">[mcu_doc0743]</p>	Pin	Function	Additional information	MD2,MD1,MD0	Mode pin	Setting MD2=1, MD1=1, and MD0=0 to enter the serial programming mode.	X0,X1	Oscillation pin	As, in the serial programming mode, CPU internal operation clock is the PLL clock multiplied-by-1, the internal operation clock frequency is equal to the oscillation clock frequency. Consequently, the frequencies that can be input to the high-speed oscillation input pin for serial writing are from 4.5 MHz to 25 MHz.	Pin	Function	Additional information	MD2,MD1,MD0	Mode pin	Setting MD2=1, MD1=1, and MD0=0 to enter the serial programming mode.	X0,X1	Oscillation pin	As, in the serial programming mode, CPU internal operation clock is the PLL clock multiplied-by-1, the internal operation clock frequency is equal to the oscillation clock frequency. Consequently, the frequencies that can be input to the high-speed oscillation input pin for serial writing are from 4 MHz to 25 MHz.
Pin	Function	Additional information																		
MD2,MD1,MD0	Mode pin	Setting MD2=1, MD1=1, and MD0=0 to enter the serial programming mode.																		
X0,X1	Oscillation pin	As, in the serial programming mode, CPU internal operation clock is the PLL clock multiplied-by-1, the internal operation clock frequency is equal to the oscillation clock frequency. Consequently, the frequencies that can be input to the high-speed oscillation input pin for serial writing are from 4.5 MHz to 25 MHz.																		
Pin	Function	Additional information																		
MD2,MD1,MD0	Mode pin	Setting MD2=1, MD1=1, and MD0=0 to enter the serial programming mode.																		
X0,X1	Oscillation pin	As, in the serial programming mode, CPU internal operation clock is the PLL clock multiplied-by-1, the internal operation clock frequency is equal to the oscillation clock frequency. Consequently, the frequencies that can be input to the high-speed oscillation input pin for serial writing are from 4 MHz to 25 MHz.																		
653	APPENDIX D	<p>■Table D.9-20 XCH Ri, ea Instruction (First Byte = 7EH) is changed.</p> <ul style="list-style-type: none"> <li>• Error</li> <li>Item "A"</li> <li>Line of +A "W2+d16,A"</li> <li>• Correct</li> <li>Item "A0"</li> <li>Line of +A "@RW2+d16"</li> </ul>																		



## Corrections of Hardware Manual

# MB90480

## hm90480-cm44-10121-7e-corr-x1-00

© Fujitsu Microelectronics Europe GmbH

### Addendum, MB90480 Hardware Manual (CM44-10121-7E)

This is the Addendum for the Hardware Manual CM44-10121-7E of the MB90480 microcontroller series. It describes all known discrepancies of the MB90480 microcontroller series Hardware Manual.

Ref. Number (Internal ref. number) (Text Link)	Date  dd.mm.yy	Version No.	Chapter/Page	Description/Correction
<a href="#">HWM90480001</a>	25.06.04	1.00	6	Low power consumption mode Transition to standby mode, Standby Cancel failure behavior
<a href="#">HWM90480002</a>	25.06.04	1.00	27	I2C INTERFACE, Note added
<a href="#">HWM90480003</a>	04.08.04	1.00	3.6	Interrupt by $\mu$ DMA, usage of $\mu$ DMA

## Transition to standby mode

The definition of Standby Cancel Failure is that the CPU will execute wrong instructions when an interrupt is executed during transition to Standby mode<sup>1</sup> at a certain time.

<sup>1</sup>:Definition of Standby mode

Main sleep mode, PLL sleep mode, Sub-sleep mode  
Time base timer mode, Watch mode, Main watch mode  
Main stop mode, PLL stop mode, Sub-stop mode  
\*Main watch mode is only for MB90370 series.

In the following cases, no problem occurs:

- Standby mode is not used
- Standby mode is released only by external reset

For further information refer to Hardware Manual chapter: 'Low power consumption mode.'

## CHAPTER 27 I2C INTERFACE (ONLY MB90485 SERIES)

Restriction of specification at sending General Call Address for MCU with I2C

When using Multi-Master mode for I2C and another Master is sending a General Code Address at same time as Fujitsu MCU, an arbitration lost\* occurs after 2nd byte.

Under following conditions the restriction do not exist:

- No usage of I2C peripheral
- Usage of I2C with Single Master system
- Usage of I2C with Multi Master system, no General Call Address used
- Usage of I2C with Multi Master system, General Call Address used by Fujitsu MCU, only
- Usage of I2C with Multi Master system, General Call Address used. If the value of data, send by Fujitsu MCU, is smaller than another transfer data, the arbitration lost does not occur.

\*: If the data value is smaller than another one, oneself never has "Arbitration lost" because one with large transmission data value will have "Arbitration lost".

Chapter 3.6 Interrupt by  $\mu$ DMA

There might be problems when using  $\mu$ DMA with UART or PPG.

**1) Detailed of bug for  $\mu$ DMA transmission**

Fujitsu found the bug, as  $\mu$ DMA transmission is not operated normally for MB90480/485 series. The bug has two combinations as following.

1.  $\mu$ DMA and UART (Synchronization/Asynchronization) transmission
2.  $\mu$ DMA and PPG

Also we have already checked the combination between  $\mu$ DMA and other resource. But there was no bug for other combination.

Resource	Result
External interrupt	○
PWC0	○
PPG0/1	×
PPG2/3	×
PPG4/5	×
Input capture 0 load	○
Input capture 1 load	○
UART(Synchronization/Asynchronization) receive completed	○
UART(Synchronization/Asynchronization) transmit completed	×
Output compare 0 match	○
Output compare 1 match	○
Output compare 2 match	○
Free-run timer / Reload timer	○
SIO1	○
SIO2	○
A/D	○

Table 1. Check list of combination between  $\mu$ DMA and other resource

1-1) Detailed of bug with combination between  $\mu$ DMA and UART (Synchronization/Asynchronization) transmission

When the serial data is sent continuously from UART

(Synchronization/Asynchronization) with using  $\mu$ DMA, Fujitsu found that less bytes than set bytes is outputted for FLASH device. The root cause of this behavior is to operate continuously next  $\mu$ DMA transmission, because interrupt clear timing of UART (Synchronization/Asynchronization) transmission is delayed. However for Evaluation device, when [debug mode] is used, expected data is outputted because internal operating is low speed. And when [native mode] is used, the behavior of bug is occurred for FLASH and MASK device. And at using only UART (Synchronization/Asynchronization) (not using  $\mu$ DMA), this bug is not occurred.

1-2) Detailed of bug with combination between  $\mu$ DMA and PPG

When the output of PPG is changed continuously with using  $\mu$ DMA, Fujitsu found that expected waveform is not outputted. This behavior is the root cause of specification as interrupt source of PPG is not cleared by  $\mu$ DMA. However at using only PPG (not using  $\mu$ DMA), this bug is not occurred.

## 2) Target devices of bug

Target devices of this bug is as following.

Series	Devices
MB90480/485series	MB90F481, MB90F482, MB90V480, MB90486, MB90487, MB90487A, MB90488A, MB90F488, MB90V485

Table 2. Target devices of bug

## 3) Countermeasure and revising schedule

For this bug, Fujitsu consider that provisional countermeasure is possible by following method.

3-1) Provisional countermeasure plan with combination between uDMA and UART (Synchronization/Asynchronization) transmission (Software countermeasure)  
At using EI2OS of secret function for MB90480/485series, the behavior of bug is avoided. EI2OS has same function as uDMA, and same data transmission as uDMA is possible. However note that execution time of transmission between EI2OS and uDMA is different.

		With using uDMA		With using EI <sup>2</sup> OS	
IOA updated / fixed selection		Fixed	Updated	Fixed	Updated
BAP updated / fixed selection	Fixed	17	19	32	34
	Updated	19	21	34	36

Table 3. Execution time of transmission (Unit: Machine clock cycle)

3-2) Permanent countermeasure with combination between uDMA and UART (Synchronization/Asynchronization) transmission (Hardware revision)  
For countermeasure of bug with combination between uDMA and UART (Synchronization/Asynchronization) transmission, Fujitsu revise MB90485series as high priority. Revision schedule of MB90485series is as following. Also countermeasure device of this bug is added "B" suffix to end of part number.

Part number after revision	Providing schedule
MB90486B (MASK)	2004/08/M: from reception
MB90487B (MASK)	2004/08/M: from reception
MB90488B (MASK)	2004/08/M: from reception
MB90F488B (FLASH)	2004/08/12: provide ES
MB90V485B (EVA)	2004/08/13: provide ES

Table 4. Part number after revision and schedule

3-3) Countermeasure with combination between uDMA and PPG

Fujitsu consider as the restriction of specification for usage with combination between uDMA and PPG. Therefore Fujitsu doesn't implement permanent countermeasure (hardware revision). Use the interrupt of PPG but not uDMA.