

Device **TC1766**
Microcode **V23, V24, V25, V27**

This Flash Firmware Status Sheet describes the Flash properties of the devices depending on the implemented microcode version. Deviations from the current user documentation which are device step specific but not Flash firmware related are documented in the current Errata Sheet.

Table 1 Current Documentation

TC1766 User's Manual	V1.1	Aug. 2005
TC1766 Data Sheet	V0.7	Feb. 2007
TriCore 1 Architecture	V1.3	Oct. 2005

The 1-byte microcode version number is stored at the bit locations 103-96. This byte is accessible at LDRAM address D000 000C_H after each reset, and subject to be overwritten by user data at any time.

The version number is defined as "Vsn", contained in the byte as:

- **s** = step code (highest 4 bit, hex number). A-step = 1, B-step = 2, and so on.
- **n** = code version number (lowest 4 bit, hex number) belonging to the step (beginning with zero for every new step code).

Example: V21, V23, V3A, V3F, etc

1 History List / Change Summary

Table 2 History List

Version	Date	Remark
1.0	24.10.2005	
1.1	15.12.2005	
1.2	02.03.2006	
1.3	28.04.2006	
1.4	22.12.2006	
1.5	02.04.2007	
1.6	16.07.2007	

Table 3 Microcode version history

Microcode version	Changes
V23	Improved Functional Erase Stability vs. Voltage & Temp Range
V24	Write Delayed by Erase Function fixed; Erase & Program Verify Features
V25	Prog Time Improvement
V26	Not a productive version
V27	Boot fix for an aborted logical sector erase

The microcode version number does not use a consecutive ascending sequence, so gaps inside this numeration can occur.

Table 4 Functional Deviations

Functional Deviation	Short Description	Chg	Pg
FIRM_TC.004	DFlash write delayed by erase operation		4
FIRM_TC.005	Program While Erase can cause fails in the sector being erased		4
FIRM_TC.006	Erase and Program Verify Feature		5
FIRM_TC.007	Boot fix for an aborted logical sector erase		6
FIRM_TC.008	Erase Algorithm Abnormality for LS0..3	New	7

Table 5 Deviations from Electrical- and Timing Specification

AC/DC/ADC Deviation	Short Description	Chg	Pg
FIRM_TC.P001	Longer Flash erase time	Update	9
FIRM_TC.P002	Page programming time		10

Table 6 Application Hints

Hint	Short Description	Chg	Pg
None			

2 Functional Deviations

FIRM_TC.004 DFlash write delayed by erase operation

In case of an ongoing erase operation to one DFlash bank, any program request to the alternate DFlash bank will be delayed until the ongoing erase operation is fully completed. This behaviour is due to a Flash microcode issue and does not affect in any other way the Flash functionality or reliability.

This erratum is valid for microcode \leq V23.

Workaround

None.

FIRM_TC.005 Program While Erase can cause fails in the sector being erased

V24 and V25 are affected by this functional bug:

Per call of a `Program while Erase` (Erase Suspend Feature) the following errors may be visible after the suspended erase is terminated in the erased sector:

- either 1 page is not properly erased. This error is oftenly detectable by reading the sector (some cells in the page read 1) but also some hard to detect weak 0 bits might be generated.
- or `FSR.VER` might show up: This error flag indicates that some overerased bits inside one page of the erased sector remained unrecovered (this overerased state is not customer-detectable, e.g. it will read 0 as expected) and can cause subsequent program operations to the erased sector to be unsuccessful, (i.e. `FSR.VER` can appear again after programming a page (Prog Verify Fault) and the bits intended to be programmed might read 0). This state can only be left by an (successful) re-erase.

The program result of the `program while erase` itself is not affected and will be valid.

Workaround

1. re-erase a sector if the program while erase became necessary (until the erase process was executed without any program while erase call).
2. do not use Program while Erase

FIRM_TC.006 Erase and Program Verify Feature

Starting microcode V24, any internal errors detectable by the FSI state machine during erase sector or program page sequences will be indicated by activation of the `FSR.VER` bit before busy status is deactivated. `FSR.VER` errors will appear typically if operations are carried out violating device specs (exceeding endurance, operating temperature, supply voltages).

`FSR.VER` can be indicated in seldom cases in absence of functional or reliability problems. Always consider that even if a `VER` would indicate a severe problem, it is usually not reasonable to stop an application in the field, but wait for functional consequences to show up.

Recommendations

These recommendations are intended for optimization of functional safety applying the current generation of the `VER` feature (optional to customer application).

- Recommended action for erase-`VER` event in field / end of line erase:
 - a) Immediate clear status, to catch other successive events and distinguish from prog-`VER`
 - b) Re-erase until `VER` disappears (max up to 3 times in sequence; afterwards ignore), but take special care to fulfill operating conditions (total sector endurance, voltage, frequency, temperature not exceeded).
 - c) Regardless from `VER`: Infineon recommends to apply, in case of "end of line" flashing or firmware update, a tight-0 check by SBE counting (or preferably a tight 0+1 check for the whole sector after sector is programmed) to determine ECC off fail rate: if single bit error (SBE) count is below 10 per sector, the risk of an incorrigible double bit error (DBE) throughout retention / further operating life is considered still negligible.
- Recommended action for prog-`VER` event in field / end of line programming:

- a) Immediate clear status, to catch other successive events and distinguish from erase-VER
- b) Never reprogram the same page (disturb budget violation) without erase
- c) Count VER occurrences for each individual sector since last erase (in SRAM in volatile manner after each powerup). Up to three VER events occurring in a sector are tolerable, but take special care to fulfill operating conditions (total sector endurance, voltage, frequency, temperature not exceeded).
- d) Regardless from VER: Infineon recommends to apply in case of "end of line" flashing or firmware update a tight 0+1 check (SBE event counting) for the written page, or preferably a tight 0+1 check for the whole sector, after sector is programmed: if single bit error (SBE) count is below 10 per sector, the risk of an incorrigible double bit error (DBE) throughout retention / further operating life is considered still negligible.
- e) If the first program into a freshly erased sector shows prog-VER, preferably reerase and reprogram the sector (reerase no more than once in case of such prog-VER). Make sure not to program into sectors where erase operation was aborted (a prog-VER will be indicated when programming to an "aborted erase" sector left in overerase) and take special care to fulfill operating conditions.

FIRM TC.007 Boot fix for an aborted logical sector erase

In case of an aborted logical or physical sector erase, cells might be in an over-erased state. As the presence of a partially erased / over-erased state of the flash is not reliably detectable by the user, a reerase is mandatory whenever an erase abortion cannot be excluded.

Please also refer to the application hint: Flash_TC.H005

In case of an aborted logical sector erase other logical sectors may become unreadable. As a consequence the boot code or alternate boot info might be unreadable and the device isn't booting customer code anymore.

Starting with uCode v27 the following functional enhancement will help to keep the customer boot code accessible:

- an aborted logical sector erase will be detected after reset
- in presence of over-erased cells the affected sector will be fully programmed. The flash boot time will be considerably (<10ms) prolonged in this case
- the 'program all' functionality to an over-erased sector allows to recover the readability of the remaining logical sectors
- the 'fixed' logical sector will be read as all '1' afterwards

The FSR.VER bit will flag the detection of an aborted sector erase and it's recovery or indicate an endangered system integrity. This flag can be reset by the clear status command.

Workaround

None

FIRM_TC.008 Erase Algorithm Abnormality for LS0..3

V25 microcode is affected by the following functional bug: over-erase algorithm for erase logical sectors 0..3 applies erroneously erase verify and soft-programming substeps to extended memory range (may even affect neighboring sectors).

The consequences are:

- the logical sector to be erased will always be physically erased unnecessarily strong. This state will be recovered by the soft-programming step, but erase time is prolonged and in LS0..3 in seldom cases cell abnormalities can be emphasized/stimulated that cause up to 31 (bitline-oriented, e.g. offset address is 100_H) single bit errors reading 1 (in an ECC correctable way) in the erased logical sector accompanied with FSR.VER indication.
- neighboring sectors will not be unintentionally erased, but may be impacted by disturb (zeroes might get slightly weaker) and additional soft-

programming resulting in potential single bit errors (SBE). The potentially SBE-impacted area for logical sectors 0 to 3 is starting at next logical sectors address SA+4000_H (i.e. 004000_H, 008000_H, 00C000_H, 010000_H) and is 1C000_H wide (because erroneously the size of the whole physical sector 20000_H is applied instead of the logical sector's size 4000_H).

Workaround

Either:

- Do not use logical sector erase LS0..3 (but physical sector erase instead), if applicable.
- Disregard VER & tolerate SBE state, if less than 10 SBEs after update.

3 **Deviations from Electrical- and Timing Specification**

FIRM TC.P001 Longer Flash erase time

The Flash firmware-dependent maximum sector erase times are shown in the following table. Sector erase time is proportional to Program resp. Data Flash sector size (e.g. erase time of a 512 kB Prog Flash sector is twice the specified for a 256 kB Prog Flash sector erase time) and may increase beyond the given limits at lower CPU operating frequencies.

Table 7 Firmware dependent max Flash erase times

Flash & sector size	Microcode version	t_{ERP} / t_{ERD} (erase time)
Program Flash, 256 kB	V23	18 s
	V24	18 s
	V25	8 s ¹⁾ ; erase time may exceed the given limits below room temperature (+20°C ... -40°C: 10s)
	V27	8s; erase time may exceed the given limits below room temperature (+20°C ... -40°C: 10s)

Deviations from Electrical- and Timing Specification
Table 7 Firmware dependent max Flash erase times (cont'd)

Flash & sector size	Microcode version	t_{ERP} / t_{ERD} (erase time)
Data Flash, 16 kB	V23	2.2 s
	V24	2.2 s
	V25	1.0s; erase time may exceed the given limits below room temperature (+20°C ... -40°C: 1.25s)
	V27	1.0s; erase time may exceed the given limits below room temperature (+20°C ... -40°C: 1.25s)

- 1) When erasing a logical sector (any of LS0..3), erase time may be extended up to 2 seconds (frequency dependent) due to FIRM_TC.008.

Maximum erase time at CPU operating frequencies below 80 MHz can be calculated according to the following table:

Table 8 Relative erase time increments

Frequency [MHz]	Increment
80	0%
66	4%
60	6%
40	12%
20	30%

Example: Maximum 256kB Program Flash Erase Time for V25 at 60 MHz is 8s * 106% = 8.48s.

FIRM_TC.P002 Page programming time

The specified page programming time is 5 msec. The actual microcode dependent programming time is shown in the following table:

Table 9 Maximum Flash page programming time

Flash	Microcode version	t_{PR} (programming time)
Program Flash	V23	8 ms
	V24	8 ms
	V25	5.6 ms
	V27	5 ms (compliant with Data Sheet)
Data Flash	V23	8 ms
	V24	8 ms
	V25	5.6 ms
	V27	5 ms (compliant with Data Sheet)

4 Application Hints

None.