

# 16/32-Bit

Architecture

## XC27x4X Derivatives

16/32-Bit Single-Chip Microcontroller  
with 32-Bit Performance  
XC2000 Family / Value Line

Errata Sheet

V1.4 2009-10

Microcontrollers

**Edition 2009-10**

**Published by  
Infineon Technologies AG  
81726 Munich, Germany**

**© 2009 Infineon Technologies AG  
All Rights Reserved.**

#### **Legal Disclaimer**

The information given in this document shall in no event be regarded as a guarantee of conditions or characteristics. With respect to any examples or hints given herein, any typical values stated herein and/or any information regarding the application of the device, Infineon Technologies hereby disclaims any and all warranties and liabilities of any kind, including without limitation, warranties of non-infringement of intellectual property rights of any third party.

#### **Information**

For further information on technology, delivery terms and conditions and prices, please contact the nearest Infineon Technologies Office ([www.infineon.com](http://www.infineon.com)).

#### **Warnings**

Due to technical requirements, components may contain dangerous substances. For information on the types in question, please contact the nearest Infineon Technologies Office.

Infineon Technologies components may be used in life-support devices or systems only with the express written approval of Infineon Technologies, if a failure of such components can reasonably be expected to cause the failure of that life-support device or system or to affect the safety or effectiveness of that device or system. Life support devices or systems are intended to be implanted in the human body or to support and/or maintain and sustain and/or protect human life. If they fail, it is reasonable to assume that the health of the user or other persons may be endangered.

# 16/32-Bit

Architecture

## XC27x4X Derivatives

16/32-Bit Single-Chip Microcontroller  
with 32-Bit Performance

XC2000 Family / Value Line

### Errata Sheet

V1.4 2009-10

## Table of Contents

<b>1</b>	<b>History List / Change Summary</b>	<b>6</b>
<b>2</b>	<b>General</b>	<b>7</b>
<b>3</b>	<b>Current Documentation</b>	<b>9</b>
<b>4</b>	<b>Errata Device Overview</b>	<b>10</b>
4.1	Functional Deviations	10
4.2	Deviations from Electrical and Timing Specification	11
4.3	Application Hints	12
4.4	Documentation Updates	13
<b>5</b>	<b>Short Errata Description</b>	<b>14</b>
5.1	Functional Deviations	14
5.2	Deviations from Electrical and Timing Specification	15
5.3	Application Hints	16
5.4	Documentation Updates	17
<b>6</b>	<b>Detailed Errata Description</b>	<b>18</b>
6.1	<b>Functional Deviations</b>	<b>18</b>
	BSL_CAN_X.001	18
	ECC_X.002	18
	ESR_X.002	19
	GPT12E_X.002	20
	OCDS_X.003	21
	PARITY_X.001	22
	RESET_X.003	22
	USIC_AI.004	23
	WDT_X.002	23
6.2	<b>Deviations from Electrical and Timing Specification</b>	<b>25</b>
	SWD_X.P001	25
6.3	<b>Application Hints</b>	<b>26</b>
	ADC_AI.H002	26
	CAPCOM12_X.H001	26
	CC6_X.H001	28
	ECC_X.H001	28
	GPT12E_X.H002	28
	INT_X.H002	30
	MultiCAN_AI.H005	30
	MultiCAN_AI.H006	30
	MultiCAN_TC.H002	31
	MultiCAN_TC.H003	31
	MultiCAN_TC.H004	32

	RESET_X.H003 .....	32
	RTC_X.H003 .....	33
	USIC_AI.H001 .....	33
6.4	<b>Documentation Updates</b> .....	34
	RESET_X.D001 .....	34
	XTAL_X.D001 .....	34

# 1 History List / Change Summary

**Table 1 History List**

Version	Date	Remark <sup>1)</sup>
1.0	30.09.2008	First Errata Sheet release
1.1	30.01.2009	
1.2	10.03.2009	New Marking/Step, new Errata Sheet layout
1.3	08.06.2009	Errata No. 01488AERRA, new Marking/Step AA
1.4	12.10.2009	Errata No. 01547AERRA

1) Errata changes to the previous Errata Sheet are marked in **Chapter 5 "Short Errata Description"**.

## Trademarks

C166™, TriCore™ and DAVE™ are trademarks of Infineon Technologies AG.

### We Listen to Your Comments

Is there any information in this document that you feel is wrong, unclear or missing?  
Your feedback will help us to continuously improve the quality of this document.  
Please send your proposal (including a reference to this document) to:

[mcdocu.comments@infineon.com](mailto:mcdocu.comments@infineon.com)



## 2 General

This Errata Sheet describes the deviations of the XC27x4X Derivatives from the current user documentation.

Each erratum identifier follows the pattern **Module\_Arch.TypeNumber**:

- **Module**: subsystem, peripheral, or function affected by the erratum
- **Arch**: microcontroller architecture where the erratum was firstly detected.
  - **AI**: Architecture Independent
  - **CIC**: Companion ICs
  - **TC**: TriCore
  - **X**: XC166 / XE166 / XC2000 Family
  - **XC8**: XC800 Family
  - **[none]**: C166 Family
- **Type**: category of deviation
  - **[none]**: Functional Deviation
  - **P**: Parametric Deviation
  - **H**: Application Hint
  - **D**: Documentation Update
- **Number**: ascending sequential number within the three previous fields. As this sequence is used over several derivatives, including already solved deviations, gaps inside this enumeration can occur.

This Errata Sheet applies to all temperature and frequency versions and to all memory size variants of this device, unless explicitly noted otherwise.

*Note: This device is equipped with a C166S V2 Core. Some of the errata have workarounds which are possibly supported by the tool vendors. Some corresponding compiler switches need possibly to be set. Please see the respective documentation of your compiler. For effects of issues related to the on-chip debug system, see also the documentation of the debug tool vendor.*

Some errata of this Errata Sheet do not refer to all of the XC27x4X Derivatives, please look to the overview:

**Table 2** for Functional Deviations

**Table 3** for Deviations from Electrical and Timing Specification

**Table 4** for Application Hints

**Table 5** for Documentation Updates



### **3 Current Documentation**

The Infineon XC2000 Family comprises device types from the XC2200 group, the XC2300 group and the XC2700 group. The XC27x4X device types belong to the XC2700 group.

Device	XC27x4X
Marking/Step	EES-AA, ES-AA, AA
Package	PG-LQFP-64, PG-LQFP-100

This Errata Sheet refers to the following documentation:

- XC27x4X Derivatives User's Manual
- XC2734X Data Sheet
- XC2764X Data Sheet
- Documentation Addendum (if applicable)

Make sure you always use the corresponding documentation for this device available in category 'Documents' at [www.infineon.com/xc2700](http://www.infineon.com/xc2700).

The specific test conditions for EES and ES are documented in a separate Status Sheet.

*Note: Devices marked with EES or ES are engineering samples which may not be completely tested in all functional and electrical characteristics, therefore they should be used for evaluation only.*

## 4 Errata Device Overview

This chapter gives an overview of the dependencies of individual errata to devices and steps. An **X** in the column of the sales codes shows that this erratum is valid.

### 4.1 Functional Deviations

**Table 2** shows the dependencies of functional deviations in the derivatives.

**Table 2 Errata Device Overview:  
Functional Deviations**

Functional Deviation	XC27x4X		
	EES-AA ES-AA	AA <sup>1)</sup>	
<b>BSL_CAN_X.001</b>	<b>X</b>	<b>X</b>	
<b>ECC_X.002</b>	<b>X</b>		
<b>ESR_X.002</b>	<b>X</b>	<b>X</b>	
<b>GPT12E_X.002</b>	<b>X</b>	<b>X</b>	
<b>OCDS_X.003</b>	<b>X</b>	<b>X</b>	
<b>PARITY_X.001</b>	<b>X</b>	<b>X</b>	
<b>RESET_X.003</b>	<b>X</b>	<b>X</b>	
<b>USIC_AI.004</b>	<b>X</b>	<b>X</b>	
<b>WDT_X.002</b>	<b>X</b>	<b>X</b>	

1) From EES/ES-AA step to AA step, 2 errata have been fixed.

## 4.2 Deviations from Electrical and Timing Specification

**Table 3** shows the dependencies of deviations from the electrical and timing specification in the derivatives.

**Table 3 Errata Device Overview:  
Deviations from Electrical and Timing Specification**

AC/DC/ADC Deviation	XC27x4X		
	EES-AA	ES-AA	AA <sup>1)</sup>
	ES-AA		
SWD_X.P001	X		

1) From EES/ES-AA step to AA step, 2 errata have been fixed.

### 4.3 Application Hints

**Table 4** shows the dependencies of application hints in the derivatives.

**Table 4 Errata Device Overview:  
Application Hints**

Hint	XC27x4X		
	EES-AA ES-AA	AA <sup>1)</sup>	
ADC_AI.H002	X	X	
CAPCOM12_X.H001	X	X	
CC6_X.H001	X	X	
ECC_X.H001	X	X	
GPT12E_X.H002	X	X	
INT_X.H002	X	X	
MultiCAN_AI.H005	X	X	
MultiCAN_AI.H006	X	X	
MultiCAN_TC.H002	X	X	
MultiCAN_TC.H003	X	X	
MultiCAN_TC.H004	X	X	
RESET_X.H003	X	X	
RTC_X.H003	X	X	
USIC_AI.H001	X	X	

1) From EES/ES-AA step to AA step, 2 errata have been fixed.

## 4.4 Documentation Updates

**Table 5** shows the dependencies of documentation updates in the derivatives.

**Table 5 Errata Device Overview:  
Documentation Updates**

Documentation Updates	XC27x4X		
	EES-AA ES-AA	AA <sup>1)</sup>	
<a href="#">RESET_X.D001</a>	X	X	
<a href="#">XTAL_X.D001</a>	X	X	

1) From EES/ES-AA step to AA step, 2 errata have been fixed.

## 5 Short Errata Description

This chapter gives an overview on the deviations and application hints. Changes to the last Errata Sheet are shown in the column “Chg”.

### 5.1 Functional Deviations

**Table 6** shows a short description of the functional deviations.

**Table 6 Functional Deviations**

Functional Deviation	Short Description	Chg	Pg
<a href="#">BSL_CAN_X.001</a>	<a href="#">Quartz Crystal Settling Time after PORST too Long for CAN Bootstrap Loader</a>		<a href="#">18</a>
<a href="#">ECC_X.002</a>	<a href="#">Incorrect ECC Error Indication for DPRAM</a>		<a href="#">18</a>
<a href="#">ESR_X.002</a>	<a href="#">ESREXSTAT1 and ESREXSTAT2 Status Bits can be Cleared after a Write Access</a>		<a href="#">19</a>
<a href="#">GPT12E_X.002</a>	<a href="#">Effects of GPT Module Microarchitecture</a>		<a href="#">20</a>
<a href="#">OCDS_X.003</a>	<a href="#">Peripheral Debug Mode Settings cleared by Reset</a>	Up-date	<a href="#">21</a>
<a href="#">PARITY_X.001</a>	<a href="#">PMTSR Register Initialization</a>		<a href="#">22</a>
<a href="#">RESET_X.003</a>	<a href="#">P2.[2:0] and P10.[12:0] Switch to Input</a>		<a href="#">22</a>
<a href="#">USIC_AI.004</a>	<a href="#">Receive shifter baudrate limitation</a>		<a href="#">23</a>
<a href="#">WDT_X.002</a>	<a href="#">Clearing the Internal Flag which Stores Preceding WDT Reset Request</a>		<a href="#">23</a>

## 5.2 Deviations from Electrical and Timing Specification

**Table 7** shows a short description of the electrical- and timing deviations from the specification.

**Table 7 Deviations from Electrical and Timing Specification**

AC/DC/ADC Deviation	Short Description	Chg	Pg
SWD_X.P001	Supply Watchdog Level $V_{\text{SWD\_min}}$ too Low		25

## 5.3 Application Hints

**Table 8** shows a short description of the application hints.

**Table 8 Application Hints**

Hint	Short Description	Chg	Pg
<b>ADC_AI.H002</b>	<b>Minimizing Power Consumption of an ADC Module</b>	New	<b>26</b>
<b>CAPCOM12_X.H001</b>	<b>Enabling or Disabling Single Event Operation</b>		<b>26</b>
<b>CC6_X.H001</b>	<b>Modifications of Bit MODEN in Register CCU6x_KSCFG</b>		<b>28</b>
<b>ECC_X.H001</b>	<b>ECC Error Indication Permanently Set</b>		<b>28</b>
<b>GPT12E_X.H002</b>	<b>Reading of Concatenated Timers</b>		<b>28</b>
<b>INT_X.H002</b>	<b>Increased Latency for Hardware Traps</b>		<b>30</b>
<b>MultiCAN_AI.H005</b>	<b>TxD Pulse upon short disable request</b>		<b>30</b>
<b>MultiCAN_AI.H006</b>	<b>Time stamp influenced by resynchronization</b>		<b>30</b>
<b>MultiCAN_TC.H002</b>	<b>Double Synchronization of receive input</b>		<b>31</b>
<b>MultiCAN_TC.H003</b>	<b>Message may be discarded before transmission in STT mode</b>		<b>31</b>
<b>MultiCAN_TC.H004</b>	<b>Double remote request</b>		<b>32</b>
<b>RESET_X.H003</b>	<b>How to Trigger a PORST after an Internal Failure</b>		<b>32</b>
<b>RTC_X.H003</b>	<b>Changing the RTC Configuration</b>		<b>33</b>
<b>USIC_AI.H001</b>	<b>FIFO RAM Parity Error Handling</b>		<b>33</b>



## 5.4 Documentation Updates

**Table 9** gives a short description of the documentation updates.

**Table 9 Documentation Updates**

Documentation Updates	Short Description	Chg	Pg
<b>RESET_X.D001</b>	<b>Reset Types of Trap Registers</b>	New	<b>34</b>
<b>XTAL_X.D001</b>	<b>Input Voltage Amplitude <math>V_{AX1}</math> on XTAL1</b>	New	<b>34</b>

## **6 Detailed Errata Description**

This chapter provides a detailed description for each erratum. If applicable a workaround is suggested.

### **6.1 Functional Deviations**

#### **BSL\_CAN\_X.001 Quartz Crystal Settling Time after PORST too Long for CAN Bootstrap Loader**

The startup configuration of the CAN bootstrap loader when called immediately after  $\overline{\text{PORST}}$  limits the settling time of the external oscillation to 0.5 ms. For typical quartz crystal this settling time is too short. The CAN bootstrap loader generates a time-out and goes into Startup Error State.

##### **Workaround**

- For low performance CAN applications a ceramic resonator with settling time less than 0.5 ms can be used.
- An alternative is the Internal Start from on-chip Flash memory as startup mode after  $\overline{\text{PORST}}$ . Then switch the system clock to external source and trigger a software reset with CAN bootstrap loader mode selected. Now the device starts with a CAN bootstrap loader without limitation of the oscillator settling time.

#### **ECC\_X.002 Incorrect ECC Error Indication for DPRAM**

Under certain conditions, the ECC error flag for the dual port memory (DPRAM) may indicate an error when none exists.

Conditions under which ECC error is incorrectly indicated:

- ECC memory protection has been selected for DPRAM ( $\text{SCU\_MCHKCON.SELDP} = 0$ ).
- The ECC check is enabled for DPRAM ( $\text{SCU\_ECCCON.DPEN} = 1$ ).

**Detailed Errata Description**

- A concurrent read and write access is made to the same byte or word in the DPRAM (possible due to instruction pipeline).

Under the above conditions, an ECC error may be indicated for DPRAM (flag `SCU_ECCSTAT.DP = 1`), although there is no error in DPRAM.

It should be noted that despite the incorrect ECC error indication, the data are delivered error free, and the ECC logic still functions correctly (correcting data single bit errors, if present).

There is no data corruption in this case. The ECC bits that were written are generated correctly, as well as check and correction is not affected for that was read.

This problem is limited to the DPRAM. All other SRAM memories cannot perform concurrent read and write accesses, and therefore cannot have this issue.

**Workaround**

Use parity protection for DPRAM (`SCU_MCHKCON.SELDP = 1`).

Single-bit errors will be correctly indicated by parity logic, but will not be corrected.

**ESR\_X.002 ESREXSTAT1 and ESREXSTAT2 Status Bits can be Cleared after a Write Access**

During a write access to any register, bits in registers `ESREXSTAT1/2` can be cleared inadvertently.

`ESREXSTAT1/2` store event(s) that can trigger various ESR functions.

**Workaround**

Make sure that the trigger signals are still active when the associated service routine runs, so the trigger source can be evaluated by software.

**GPT12E\_X.002 Effects of GPT Module Microarchitecture**

The present GPT module implementation provides some enhanced features (e.g. block prescalers  $BPS1$ ,  $BPS2$ ) while still maintaining timing and functional compatibility with the original implementation in the C166 Family of microcontrollers.

Both the GPT1 and GPT2 blocks use a finite state machine to control the actions within each block. Since multiple interactions are possible between the timers ( $T2 \dots T6$ ) and register CAPREL, these elements are processed sequentially within each block in different states. However, all actions are normally completed within one basic clock cycle.

The GPT2 state machine has 4 states (2 states when  $BPS2 = 01_B$ ) and processes  $T6$  before  $T5$ . The GPT1 state machine has 8 states (4 states when  $BPS1 = 01_B$ ) and processes the timers in the order  $T3 - T2$  (all actions except capture) -  $T4 - T2$  (capture).

In the following, two effects of the internal module microarchitecture that may require special consideration in an application are described in more detail.

**1.) Reading T3 by Software with T2/T4 in Reload Mode**

When  $T2$  or  $T4$  are used to reload  $T3$  on overflow/underflow, and  $T3$  is read by software on the fly, the following unexpected values may be read from  $T3$ :

- when  $T3$  is counting **up**,  $0000_H$  or  $0001_H$  may be read from  $T3$  directly after an overflow, although the reload value in  $T2/T4$  is higher ( $0001_H$  may be read in particular if  $BPS1 = 01_B$  and  $T3I = 000_B$ ),
- when  $T3$  is counting **down**,  $FFFF_H$  or  $FFFE_H$  may be read from  $T3$  directly after an underflow, although the reload value in  $T2/T4$  is lower ( $FFFE_H$  may be read in particular if  $BPS1 = 01_B$  and  $T3I = 000_B$ ).

*Note: All timings derived from  $T3$  in this configuration (e.g. distance between interrupt requests, PWM waveform on  $T3OUT$ , etc.) are accurate except for the specific case described under 2.) below.*

**Workaround:**

- When  $T3$  counts **up**, and  $value\_x < reload$  value is read from  $T3$ ,  $value\_x$  should be replaced with the reload value for further calculations.

**Detailed Errata Description**

- When T3 counts **down**, and `value_x > reload` value is read from T3, `value_x` should be replaced with the reload value for further calculations.

Alternatively, if the intention is to identify the overflow/underflow of T3, the T3 interrupt request may be used.

**2.) Reload of T3 from T2 with setting  $BPS1 = 01_B$  and  $T3I = 000_B$** 

When T2 is used to reload T3 in the configuration with  $BPS1 = 01_B$  and  $T3I = 000_B$  (i.e. fastest configuration/highest resolution of T3), the reload of T3 is performed with a delay of one basic clock cycle.

**Workaround 1:**

To compensate the delay and achieve correct timing,

- increment the reload value in T2 by 1 when T3 is configured to count **up**,
- decrement the reload value in T2 by 1 when T3 is configured to count **down**.

**Workaround 2:**

Alternatively, use T4 instead of T2 as reload register for T3. In this configuration the reload of T3 is not delayed, i.e. the effect described above does not occur with T4.

**OCDS\_X.003 Peripheral Debug Mode Settings cleared by Reset**

The behavior (run/stop) of the peripheral modules in debug mode is defined in bitfield SUMCFG in the KSCCFG registers. The intended behavior is, that after an application reset has occurred during a debug session, a peripheral re-enters the mode defined for debug mode.

For some peripherals, the debug mode setting in SUMCFG is erroneously set to normal mode upon any reset (instead upon a debug reset only). It remains in this state until SUMCFG is written by software or the debug system.

Some peripherals will **not** re-enter the state defined for debug mode after an application reset:

**GPT12, CAPCOM2, and MultiCAN** will resume normal operation like after reset, i.e. they are inactive until they are initialized by software.

**Detailed Errata Description**

In case the **RTC** has been running before entry into debug mode, and it was configured in SUMCFG to stop in debug mode, it will resume operation as before entry into debug mode instead.

All other peripheral modules, i.e. ADC, CCU6 and USIC, will correctly re-enter the state defined for debug mode after an application reset in debug mode.

For **Flash** and **CPU**, bitfield SUMCFG must be configured to normal mode anyway, since they are required for debugging.

**Workaround**

None.

**PARITY\_X.001 PMTSR Register Initialization**

The PMTSR register content after start-up is 0100<sub>H</sub>, meaning the parity logic for SBRAM is not in standard mode of operation.

**Workaround**

If parity will be used as Memory Control mechanism for SBRAM, it must be enabled by initializing the PMTSR register with 8000<sub>H</sub>.

**RESET\_X.003 P2.[2:0] and P10.[12:0] Switch to Input**

During the execution of an Application Reset and Debug Reset the pins P2.[2:0] and P10.[12:0] are intermediately switched to input.

These pins return to their previous mode approximately 35 system clock cycles after the application reset counter has expired (approx. 0.6 µs with default reset delay at 80 MHz).

If such a pin is used as output, make sure that this short interruption does not lead to critical system conditions.

**Workaround**

External pull devices can be added to have a defined level on these pins during Application and Debug Reset.

**USIC AI.004 Receive shifter baudrate limitation**

If the frame length of `SCTRH.FLE` does not match the frame length of the master, then the baudrate of the SSC slave receiver is limited to  $f_{\text{sys}}/2$  instead of  $f_{\text{sys}}$ .

**Workaround**

None.

**WDT X.002 Clearing the Internal Flag which Stores Preceding WDT Reset Request**

The information that the WDT has already been exceeded once is stored in an internal flag. In contrary to the documentation, that this flag can be cleared by writing a 1<sub>B</sub> to bit `WDTCS.CLRIRF` at any time, clearing of the internal flag is only possible, when the WDT is in Prewarning Mode.

**Workaround 1**

Applications following the proposal of Application Note **AP16103** (section 'Using ESR pins to trigger a PORST reset') to trigger a Power-on Reset upon a WDT event will find the internal flag cleared upon the Power-on Reset and thus will have no issue with this limitation.

**Workaround 2**

In case the WDT triggers a User Reset upon a WDT overflow, the internal flag will not be cleared by the reset itself. Any further overflow of the WDT will lead to a permanent reset of the device.

Applications which intentionally let the WDT exceed once, e.g. in conjunction with an initial self test, might want to have the internal flag cleared to prevent a permanent reset upon a real WDT overflow.

If the internal flag shall be cleared by software, this must be done as a reaction on a WDT overflow in the time frame the WDT is in Prewarning Mode before the permanent User Reset will be triggered. The CPU is notified upon the WDT entering Prewarning Mode by issuing an interrupt request. The application can

react on this request and clear the internal flag now by writing a 1<sub>B</sub> to bit `WDTCS.CLRIRF` e.g. within an ISR.

### **Workaround 3**

Some applications may not want to use or rely on the interrupt logic in conjunction with a WDT overflow event. The proposed remedy in this case is, to initiate a Power Reset to clear the internal flag by changing the settings of the active Supply Watchdog (SWD) as follows:

1. Disable SFR protection.
2. Write the inverted value of bit `LxALEV` to register `SWDCON0`, where x stands for the number of the comparator which currently would trigger a Power Reset.

In doing so, a Power Reset for `VDDI_1` and `VDDI_M` will be activated clearing the internal flag. The application may store information on preceding WDT events in the Standby-SRAM. This can be done any time after the WDT reset without timing limitations or the need to use the interrupt logic.

*Note: Although the supply for the DPRAM, DSRAM and PSRAM will be switched off during the active reset phase, it depends on the external buffer capacitance at the `VDDI_1` pins, the actual system clock frequency and the environmental conditions, whether the content of these RAMs will be preserved in this case or not. However, the Standby-RAM itself is not cleared upon this reset.*



## 6.2 Deviations from Electrical and Timing Specification

### **SWD\_X.P001 Supply Watchdog Level $V_{\text{SWD\_min}}$ too Low**

The supply watchdog (SWD) has a built-in hysteresis. In the affected products, this hysteresis is increased.

This leads to a decreased lower level, i.e. the threshold is lower than selected (e.g.  $< 4.5 \text{ V}$  for  $\text{SWDCON.LEV}_{\text{xV}} = 1001_{\text{B}}$ , or  $< 3.0 \text{ V}$  for  $\text{SWDCON.LEV}_{\text{xV}} = 0001_{\text{B}}$ ).

The functionality of the on-chip modules is not affected, as it is ensured by the power validation circuits (PVC).

The IO timing can be marginally slower if  $V_{\text{DDP}}$  is below the specified minimum value.

#### **Workaround**

None.

## 6.3 Application Hints

### **ADC\_AI.H002 Minimizing Power Consumption of an ADC Module**

For a given number of A/D conversions during a defined period of time, the total energy (power over time) required by the ADC analog part during these conversions via supply  $V_{DDPA}$  is approximately proportional to the converter active time.

#### **Recommendation for Minimum Power Consumption:**

In order to minimize the contribution of A/D conversions to the total power consumption, it is recommended

1. to select the internal operating frequency of the analog part ( $f_{ADC1}$ ) near the **maximum** value specified in the Data Sheet, and
2. to switch the ADC to a power saving state (via `ANON`) while no conversions are performed. Note that a certain wake-up time is required before the next set of conversions when the power saving state is left.

*Note: The selected internal operating frequency of the analog part that determines the conversion time will also influence the sample time  $t_S$ . The sample time  $t_S$  can individually be adapted for the analog input channels via bit field `STC`.*

### **CAPCOM12\_X.H001 Enabling or Disabling Single Event Operation**

The single event operation mode of the CAPCOM1/2 unit eliminates the need for software to react after the first compare match when only one event is required within a certain time frame. The enable bit `SEEy` for a channel `CCy` is cleared by hardware after the compare event, thus disabling further events for this channel.

#### **One Channel in Single Event Operation**

As the Single Event Enable registers `CC1_SEE`, `CC2_SEE` are not located in the bit-addressable SFR address range, they can only be modified by instructions

operating on data type WORD. This is no problem when only one channel of a CAPCOM unit is used in single event mode.

### **Two or more Channels in Single Event Operation**

When two or more channels of a CAPCOM unit are independently operating in single event mode, usually an OR instruction is used to enable one or more compare events in register `CCn_SEE`, while an AND instruction may be used to disable events before they have occurred. In these cases, the timing relation of the channels must be considered, otherwise the following typical problem may occur:

- In the Memory stage, software reads register `CCn_SEE` with bit `SEEy = 1B` (event for channel `CCy` has not yet occurred)
- Meanwhile, event for `CCy` occurs, and bit `SEEy` is cleared to `0B` by hardware
- In the Write-Back stage, software writes `CCn_SEE` with bit `SEEx = 1B` (intended event for `CCx` enabled via OR instruction) **and** bit `SEEy = 1B`
- or, as inverse procedure, software writes `CCn_SEE` with bit `SEEx = 0B` (intended event for `CCx` disabled via AND instruction) **and** bit `SEEy = 1B`

In these cases, another unintended event for channel `CCy` is enabled.

To avoid this effect, one of the following solutions - depending on the characteristics of the application - is recommended to enable or disable further compare events for CAPCOM channels concurrently operating in single event mode:

- Modify register `CCn_SEE` only when it is ensured that no compare event in single event mode can occur, i.e. when `CCn_SEE = 0x0000`, or
- Modify register `CCn_SEE` only when it is ensured that there is a sufficient time distance to the events of all channels operating in single event mode, such that none of the bits in `CCn_SEE` can change in the meantime, or
- Use single event operation for one channel only (i.e. only one bit `SEMx` may be = `1B`), and/or
- Use one of the standard compare modes, and emulate single event operation for a channel `CCs` by disabling further compare events in bit field `MODs` (in register `CCn_Mz`) in the corresponding interrupt service routine. Writing to register `CCn_Mz` is uncritical, as this register is not modified by hardware.

**CC6\_X.H001 Modifications of Bit MODEN in Register CCU6x\_KSCFG**

For each module, setting bit MODEN = 0 immediately switches off the module clock. Care must be taken that the module clock is only switched off when the module is in a defined state (e.g. stop mode) in order to avoid undesired effects in an application.

In addition, for a CCU6 module in particular, if bit MODEN is changed to 0 while the internal functional blocks have not reached their defined stop conditions, and later MODEN is set to 1 and the mode is not set to run mode, this leads to a lock situation where the module clock is not switched on again.

**ECC\_X.H001 ECC Error Indication Permanently Set**

The ECC error flag of the `ECCSTAT` register for the DPRAM, DSRAM, PSRAM and SBRAM can not be cleared, if a memory location with an ECC error is selected and the ECC is enabled. The memory can be selected by an active or by the latest read or write access.

**Workaround**

Select a memory location without ECC error in the respective memory (e.g. make a read to another address) and then clear the ECC error flag. Be aware that the new selected address may also have an ECC error.

**GPT12E\_X.H002 Reading of Concatenated Timers**

For measuring longer time periods, a core timer (T3 or T6) may be concatenated with an auxiliary timer (T2/T4 or T5) of the same timer block. In this case, the core timer contains the low part, and the auxiliary timer contains the high part of the extended timer value.

When reading the low and high parts of concatenated timers, care must be taken to obtain consistent values in particular after a timer overflow/underflow (e.g. one part may already have considered an overflow, while the other has

**Detailed Errata Description**

not). This is a general issue when reading multi-word results with consecutive instructions, and not necessarily unique to the GPT module microarchitecture.

The following algorithm may be used to read concatenated GPT timers, represented by Timer\_high (for auxiliary timer, here: T2) and Timer\_low (for core timer, here: T3). In this example, the high part is read twice, and reading of the low part is repeated if two different values were read for the high part.

- read Timer\_high\_temp = T2
- read Timer\_low = T3
- wait two basic clock cycles (to allow increment/decrement of auxiliary timer in case of core timer overflow/underflow) - see [Table 10](#) below
- read Timer\_high = T2
  - if Timer\_high is not equal to Timer\_high\_temp: read Timer\_low = T3

After execution of this algorithm, Timer\_high and Timer\_low represent a consistent time stamp of the concatenated timers.

The equivalent number of system clock cycles corresponding to two basic clock cycles is shown in the following [Table 10](#):

**Table 10      Equivalent Number of System Clock Cycles Required to Wait for Two Basic Clock Cycles**

<b>Setting of BPS1</b>	<b>BPS1 = 01</b>	<b>BPS1 = 00</b>	<b>BPS1 = 11</b>	<b>BPS1 = 10</b>
Required Number of System Clocks	8	16	32	64
<b>Setting of BPS2</b>	<b>BPS2 = 01</b>	<b>BPS2 = 00</b>	<b>BPS2 = 11</b>	<b>BPS2 = 10</b>
Required Number of System Clocks	4	8	16	32

In case the required timer resolution can be achieved with different combinations of the Block Prescaler BPS1/BPS2 and the Individual Prescalers T×I, the variant with the smallest value for the Block Prescaler may be chosen to minimize the waiting time. E.g. in order to run T6 at  $f_{SYS}/512$ , select BPS2 = 00<sub>B</sub>, T6I = 111<sub>B</sub>, and insert 8 NOPs (or other instructions) to ensure the required waiting time before reading Timer\_high the second time.

**INT\_X.H002 Increased Latency for Hardware Traps**

When a condition for a HW trap occurs (i.e. one of the bits in register TFR is set to 1<sub>B</sub>), the next valid instruction that reaches the Memory stage is replaced with the corresponding `TRAP` instruction. In some special situations described in the following, a valid instruction may not immediately be available at the Memory stage, resulting in an increased delay in the reaction to the trap request:

1. When the CPU is in break mode, e.g. single-stepping over such instructions as `SBRK` or `BSET TFR.x` (where `x` = one of the trap flags in register TFR) will have no (immediate) effect until the next instruction enters the Memory stage of the pipeline (i.e. until a further single-step is performed).
2. When the pipeline is running empty due to (mispredicted) branches and a relatively slow program memory (with many wait states), servicing of the trap is delayed by the time for the next access to this program memory, even if vector table and trap handler are located in a faster memory. However, the situation when the pipeline/prefetcher are completely empty is quite rare due to the advanced prefetch mechanism of the C166S V2 core.

**MultiCAN\_AI.H005 TxD Pulse upon short disable request**

If a CAN disable request is set and then canceled in a very short time (one bit time or less) then a dominant transmit pulse may be generated by MultiCAN module, even if the CAN bus is in the idle state.

Example for setup of the CAN disable request:

`MCAN_KSCCFG.MODEN = 0` and then `MCAN_KSCCFG.MODEN = 1`

**Workaround**

Set all INIT bits to 1 before requesting module disable.

**MultiCAN\_AI.H006 Time stamp influenced by resynchronization**

The time stamp measurement feature is not based on an absolute time measurement, but on actual CAN bit times which are subject to the CAN

**Detailed Errata Description**

resynchronization during CAN bus operation. The time stamp value merely indicates the number of elapsed actual bit times. Those actual bit times can be shorter or longer than nominal bit time length due to the CAN resynchronization events.

**Workaround**

None.

**MultiCAN TC.H002 Double Synchronization of receive input**

The MultiCAN module has a double synchronization stage on the CAN receive inputs. This double synchronization delays the receive data by 2 module clock cycles. If the MultiCAN is operating at a low module clock frequency and high CAN baudrate, this delay may become significant and has to be taken into account when calculating the overall physical delay on the CAN bus (transceiver delay etc.).

**MultiCAN TC.H003 Message may be discarded before transmission in STT mode**

If `MOFCRn.STT=1` (Single Transmit Trial enabled), bit TXRQ is cleared (TXRQ=0) as soon as the message object has been selected for transmission and, in case of error, no retransmission takes places.

Therefore, if the error occurs between the selection for transmission and the real start of frame transmission, the message is actually never sent.

**Workaround**


In case the transmission shall be guaranteed, it is not suitable to use the STT mode. In this case, `MOFCRn.STT` shall be 0.

### **MultiCAN\_TC.H004 Double remote request**

Assume the following scenario: A first remote frame (dedicated to a message object) has been received. It performs a transmit setup (TXRQ is set) with clearing NEWDAT. MultiCAN starts to send the receiver message object (data frame), but loses arbitration against a second remote request received by the same message object as the first one (NEWDAT will be set).

When the appropriate message object (data frame) triggered by the first remote frame wins the arbitration, it will be sent out and NEWDAT is not reset. This leads to an additional data frame, that will be sent by this message object (clearing NEWDAT).

There will, however, not be more data frames than there are corresponding remote requests.



**Figure 1 Loss of Arbitration**

### **RESET\_X.H003 How to Trigger a PORST after an Internal Failure**

There is no internal User Reset that restores the complete device including the power system like a Power-On Reset. In some applications it is possible to connect ESR1 or ESR2 with the PORST pin and set the used ESR pin as Reset output. With this a WDT or Software Reset can trigger a Power-On Reset.

A detailed description is in the Application Note **AP16103**.



**RTC\_X.H003 Changing the RTC Configuration**

The count input clock  $f_{\text{RTC}}$  for the Real Time Clock module (RTC) can be selected via bit field `RTCCLKSEL` in register `RTCCLKCON`. Whenever the system clock is less than 4 times faster than the RTC count input clock ( $f_{\text{SYS}} < f_{\text{RTC}} \times 4$ ), Asynchronous Mode must be selected (bit `RTCCM` = `1B` in register `RTCCLKCON`).

To assure data consistency in the count registers `T14`, `RTCL`, `RTCH`, the RTC module must be temporarily switched off by setting bit `MODEN` = `0B` in register `RTC_KSCCFG` before register `RTCCLKCON` is modified, i.e. whenever

- changing the operating mode (Synchronous/Asynchronous) Mode in bit `RTCCM`, or
- changing the RTC count source in bit field `RTCCLKSEL`.

In case power domain `DMP_1` is switched off, it is not required to switch the RTC to Asynchronous Mode, since it will receive a reset in any case.

**USIC\_AI.H001 FIFO RAM Parity Error Handling**

A false RAM parity error may be signalled by the USIC module, which may optionally lead to a trap request (if enabled) for the USIC RAM, under the following conditions:

- a receive FIFO buffer is configured for the USIC module, and
- after the last power-up, less data elements than configured in bit field `SIZE` have been received in the FIFO buffer, and
- the last data element is read from the receiver buffer output register `OUTRL` (i.e. the buffer is empty after this read access).

Once the number of received data elements is greater than or equal to the receive buffer size configured in bit field `SIZE`, the effect described above can no longer occur.

To avoid false parity errors, it is recommended to initialize the USIC RAM before using the receive buffer FIFO. This can be achieved by configuring a 64-entry transmit FIFO and writing 64 times the value `0x0` to the FIFO input register `IN00` to fill the whole FIFO RAM with `0x0`.

## 6.4 Documentation Updates

### RESET\_X.D001 Reset Types of Trap Registers

The reset type of SCU registers TRAPDIS, TRAPSET, TRAPNP and TRAPNP1 is an Application Reset.

In the next revision of the user's manual the reset type of this registers will be changed from a Power-on Reset to an Application Reset.

### XTAL\_X.D001 Input Voltage Amplitude $V_{AX1}$ on XTAL1

In the Data Sheet section "External Clock Input Parameters" the following table and figure should be updated (major changes are marked **red**).

**Table 11 Start-Up Mode Configuration**


Parameter	Symbol	Values			Unit	Note / Test Condition
		Min.	Typ.	Max.		
Oscillator frequency	$f_{osc}$ SR	4	-	40	MHz	Input=Clock Signal
		4	-	16	MHz	Input=crystal or ceramic resonator
Input voltage amplitude on XTAL1 <sup>1)</sup>	$V_{AX1}$ SR	$0.3 \times V_{DDIM}$	-	-	V	4 to 16 MHz
		<b><math>0.4 \times V_{DDIM}</math></b>	-	-	V	16 to 25 MHz
		<b><math>0.5 \times V_{DDIM}</math></b>	-	-	V	25 to 40MHz

- 1) The amplitude voltage  $V_{AX1}$  refers to the offset voltage  $V_{OFF}$ . This offset voltage must be stable during the operation and the resulting voltage peaks must remain within the limits defined by  $V_{IX1}$ .

*Note: For crystal or ceramic resonator operation, it is strongly recommended to measure the oscillation allowance (negative resistance) in the final target*

system (layout) to determine the optimum parameters for oscillator operation.

The manufacturers of crystals and ceramic resonators offer an oscillator evaluation service. This evaluation checks the crystal/resonator specification limits to ensure a reliable oscillator operation.



**Figure 2 External Clock Drive XTAL1**

[www.infineon.com](http://www.infineon.com)