

Errata Sheet

June 1, 1999 / Release 1.1

Device:	C517A-4R
Stepping Code / Marking:	AA
Package:	P-LCC-84, P-MQFP-100

This Errata Sheet describes the deviations from the current user documentation. The classification and numbering system is module oriented in a continual ascending sequence over several derivatives, as well already solved deviations are included. So gaps inside this enumeration could occur.

The current documentation is: Data Sheet 10.97
User's Manual 01.99
Instruction Set Manual 05.98

Note: Devices marked with EES- or ES are engineering samples which may not be completely tested in all functional and electrical characteristics, therefore they should be used for evaluation only.

The specific test conditions for EES and ES are documented in a separate Status Sheet.

Change summary to last Errata Sheet Rel. 1.0:

- **New User's Manual** (01.99) does not contain incorrect information about "wakeup from software power down" anymore.

Functional Problems:

None.

Functional Deviations:

Problem.2: EA#-pin is latched during RESET when ROM protection is enabled

In the current documentation (User's Manual 08.97) it is not mentioned that with activated ROM protection, the state of the EA#-pin is latched during RESET. Therefore switching of EA#-pin during program execution will have no effect.

Workaround:

None.

Deviation from Electrical- and Timing Specification:

None.