RELEASE NOTES

==========

Product Name : **DAvE XC23xxE_Series**
Release Version : **1.0**
Type of Release : **Release Candidate (RC)**

Important Notice:
The delivery is **not** intended to be used for production code

==========

Name of the Supplier : **Infineon Technologies**
Date of Release : **28.08.2012**

==========

List of Released Items:

Released Item	Filename	Version	Updated
DAvE DIP	XC23xxE_Series_v1_0.dip	1.0	
Software Release Notes	DAvE_XC23xxE_Series_Release_Notes_v1_0.pdf	1.0	
Installation Procedure	DAvE_XC23xxE_Series_Dip_Installation_Procedure_v1_0.pdf	1.0	

Customer Contact:

If you need any support for the software or documentation, contact Infineon Technologies AG by electronic mail:

dave@Infineon.com

System Requirements:

This release is intended to be used with

- DAvE Mother System version 2.1r22 and above
- Tasking Viper v2.5r1
- Tasking Classic v8.9r1
- Keil v7.05

Installation Instructions:

Installation instructions for installing XC23xxE_Series_v1.0 dip is provided in "DAvE_ XC23xxE_Series_Dip_Installation_Procedure_v1.0.pdf"

Changes from the previous Release Version v0.1:

List of new Features:

- Enhancements:
    - None

List of fixed Bugs:

ID	Description	Status
Issue_01	a. In P11 Future, we have 12-bit ADC but the timing information only show for 10-bit and 8 bit b. The selection for the ADC resolution only available for 10-bit and 8-bit, no selection for 12-bit ADC.	Fixed
Issue_02	When ADC1 Channel 10 is enable, there is no warning on the JTAG pin, which this warning is available when selecting ADC0 CH10. Since both channel is using the same pin, it would be wise to have the warning massage for ADC1 CH10 as well.	Fixed
Issue_03	XC2269i – USIC4 Channel1 should show none for the protocol selection. This is because there are no pins maps to this channel. This channel should be greyed out or disable as it cannot be used.	Fixed
Issue_04	The VCO frequency is not shown correctly at the PLL setting. With the default 8MHz reference frequency, the VCO should be 256MHz	Fixed
Issue_05	The Documentation drop box shows error message when clicked on user manual links – the links to be removed	Fixed

List of Limitations (incl. Workarounds):

Limitations:

- No known limitations

Notes on Release v0.1

List of Features:

- Following devices are supported
    a. XC2361E
    b. XC2367E
    c. XC2388E
- Following Compilers are supported
    a. Tasking Viper v2.5r1
    b. Tasking Classic v8.9r1
    c. Keil v7.05
- Following System Units & Peripheral Units can be configured through DAvE

a. Main (Project Settings)
b. Ports
c. Interrupt
d. SCU
e. WDT
f. USIC0/1/2/3
g. GPT1/2
h. RTC
i. ADC0/1
j. CC2
k. CCU60/61/62/63
l. MCAN

List of Limitations (incl. Workarounds):

Limitations:

- No known limitations