October 3, 2012

Silicon Errata for the CY8C21x34 PSoC® Programmable System-on-Chip™

This document describes the errata for the PSoC® Programmable System-on-Chip CY8C21x34. Details include errata trigger conditions, scope of impact, available workarounds, and silicon revision applicability. Compare this document to the device's data sheet for a complete functional description.

Contact your local Cypress Sales Representative if you have questions.

Part Numbers Affected

Part Number	Ordering Information
CY8C21x34	CY8C21234-24SXI
	CY8C21234-24SXIT
	CY8C21334-24PVXI
	CY8C21334-24PVXIT
	CY8C21534-24PVXI
	CY8C21534-24PVXIT
	CY8C21434-24LFXI
	CY8C21434-24LFXIT
	CY8C21434-24LKXI
	CY8C21434-24LKXIT
	CY8C21634-24LFXI
	CY8C21634-24LFXIT
	CY8C21434-24LTXI
	CY8C21434-24LTXIT
	CY8C21434-24LQXI
	CY8C21434-24LQXIT
	CY8C21634-24LTXI
	CY8C21634-24LTXIT
	CY8C21001-24PVXI

CY8C21x34 Qualification Status

Product Status: Production

CY8C21x34 Errata Summary

The following table defines the errata applicability to available CY8C21x34 family devices. An "X" indicates that the errata pertains to the selected device.

Note Errata items, in the table below, are hyperlinked. Click on any item entry to jump to its description.

Items	Part Number	Silicon Revision	Fix Status
[1]. Internal Main Oscillator (IMO) Tolerance Deviation at Temperature Extremes	CY8C21x34	A	No fix is currently planned.
[2]. I2C Errors	CY8C21x34	A	No fix is currently planned.

1. Internal Main Oscillator (IMO) Tolerance Deviation at Temperature Extremes

- **PROBLEM DEFINITION**

  Asynchronous Digital Communications Interfaces may fail framing beyond 0 °C to 70 °C. This problem does not affect end-product usage between 0 °C and 70 °C.

- **PARAMETERS AFFECTED**

  The IMO frequency tolerance. The worst case deviation when operated below 0 °C and above +70 °C and within the upper and lower datasheet temperature range is ±5%.

- **TRIGGER CONDITION(S)**

  The asynchronous Rx/Tx clock source IMO frequency tolerance may deviate beyond the datasheet limit of ±2.5% when operated beyond the temperature range of 0 °C to +70 °C.

- **SCOPE OF IMPACT**

  This problem may affect UART, IrDA, and FSK implementations.

- **WORKAROUND**

  Implement a quartz crystal stabilized clock source on at least one end of the asynchronous digital communications interface.

- **FIX STATUS**

  No fix is currently planned.

2. I^2C Errors

- **PROBLEM DEFINITION**

  The I^2C block exhibits occasional data and bus corruption errors when the I^2C master initiates transactions while the device is transitioning in to or out of sleep mode.

- **PARAMETERS AFFECTED**

  Affects reliability of I^2C communication to device, between I^2C master, and third party I^2C slaves.

- **TRIGGER CONDITION(S)**

  Triggered by transitions into and out of the device's sleep mode.

- **SCOPE OF IMPACT**

  This problem may affect UART, IrDA, and FSK implementations.

- **WORKAROUND**

  Firmware workarounds are available in firmware. Generally the workaround consists of disconnecting the I^2C block from the bus prior to going to sleep modes, I^2C transactions during sleep are supported by a protocol in which the master wakes the device prior to the I^2C transaction

- **FIX STATUS**

  Will not be fixed.

References

[1] Document # 38-12025, CY8C21234/CY8C21334/CY8C21434/CY8C21534/CY8C21634 PSoC® Programmable System-on-Chip™ Final Datasheet

Document History Page

Document Title: Silicon Errata for the CY8C21x34 PSoC® Programmable System-on-Chip™ Document Number: 001-48789				
Revision	**ECN**	**Submission Date**	**Orig. of Change**	**Description of Change**
**	2567361	09/16/2008	XSG/AESA	IMO tolerance deviation
*A	2763570	09/14/2009	TOF	Changed fix status.
*B	3765139	10/03/2012	ANWA	Changed title. Added Errata item #2 “I2C Errors”.

PSoC is a registered trademark of Cypress Semiconductor Corp. Programmable System-on-Chip, EZ-Color, and PSoC Designer are trademarks of Cypress Semiconductor Corp. All other trademarks or registered trademarks referenced herein are the property of their respective owners.

Cypress Semiconductor
198 Champion Court
San Jose, CA 95134-1709
Phone: 408-943-2600
Fax: 408-943-4730
http://www.cypress.com

© Cypress Semiconductor Corporation, 2008-2012. The information contained herein is subject to change without notice. Cypress Semiconductor Corporation assumes no responsibility for the use of any circuitry other than circuitry embodied in a Cypress product. Nor does it convey or imply any license under patent or other rights. Cypress products are not warranted nor intended to be used for medical, life support, life saving, critical control or safety applications, unless pursuant to an express written agreement with Cypress. Furthermore, Cypress does not authorize its products for use as critical components in life-support systems where a malfunction or failure may reasonably be expected to result in significant injury to the user. The inclusion of Cypress products in life-support systems application implies that the manufacturer assumes all risk of such use and in doing so indemnifies Cypress against all charges.

Any Source Code (software and/or firmware) is owned by Cypress Semiconductor Corporation (Cypress) and is protected by and subject to worldwide patent protection (United States and foreign), United States copyright laws and international treaty provisions. Cypress hereby grants to licensee a personal, non-exclusive, non-transferable license to copy, use, modify, create derivative works of, and compile the Cypress Source Code and derivative works for the sole purpose of creating custom software and or firmware in support of licensee product to be used only in conjunction with a Cypress integrated circuit as specified in the applicable agreement. Any reproduction, modification, translation, compilation, or representation of this Source Code except as specified above is prohibited without the express written permission of Cypress.

Disclaimer: CYPRESS MAKES NO WARRANTY OF ANY KIND, EXPRESS OR IMPLIED, WITH REGARD TO THIS MATERIAL, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE. Cypress reserves the right to make changes without further notice to the materials described herein. Cypress does not assume any liability arising out of the application or use of any product or circuit described herein. Cypress does not authorize its products for use as critical components in life-support systems where a malfunction or failure may reasonably be expected to result in significant injury to the user. The inclusion of Cypress’ product in a life-support systems application implies that the manufacturer assumes all risk of such use and in doing so indemnifies Cypress against all charges.

Use may be limited by and subject to the applicable Cypress software license agreement.