

- 1) EXCLUDE MOLD FLASH
  2) REMOVAL ON MOLD GATE, INTRUSION 0.1MM AND PROTRUSION 0.1MM
- 3) LEAD LENGTH UP TO ANTI FLASH LINE 4)ALL METAL SURFACE ARE PLATED, EXCEPT AREA OF CUT ALL DIMENSIONS ARE IN UNITS MM